Castle Point Local Highways Panel Meeting Agenda

28th November 2013 16:00hrs Committee Room 1, Castle Point Council Offices.

Panel Members:

ECC Councillors	CPBC Councillors
Dave Blackwell	Bill Dick
Ray Howard	Simon Hart
Jill Reeves	Tom Skipp
Alan Bayley	Steven Cole
Jamie Huntman	Martin Tucker

Other Attendees:

ECC:

Natalie Szpigelman - Highways Liaison Officer Beverley Gould- Senior Strategy & Engagement Officer Tony Buston- Senior Strategy & Engagement Officer

CPBC:

Trudie Bragg - Head of Environment Stuart Jarvis – Contracts Manager Cheryl Salmon- Civic Governance Officer

Time		Item	Lead:	Papers:
	1	Welcome and Introductions	Chairman	Verbal
	2	Approval of Minutes of Last Meeting 7 th October 2013	Chairman	Attached
	3	Castle Point Regeneration - Various	ME/TB	Verbal
	4	Potential Schemes for Consideration of Panel	NS	Attached
	5	Information Item- Scheme Updates inc. Benfleet Station Cycle Storage and Somnes Avenue Crossing Upgrade	NS	Attached
	6	Castle Point Cycle Routes	All	Attached
	7	Sainsburys Road Safety Scheme	NS	Attached
	8	Highways Rangers	SJ	Attached
	9	AOB	Chairman	Verbal
	10	Date of next meeting- 13 th February 2014		

CASTLE POINT LOCAL HIGHWAYS PANEL – MINUTES AND ACTIONS

		PRESENT:		
Date:	7th October 2013	Panel Members:		
	e: Committee Room 1, Castle Point al Offices, Benfleet	ECC Councillors Ray Howard (Chairman Jill Reeves (JR); CPBC Councillors Stev (SC); Bill Dick (BD); Simon Hart (SH); C (CR); and Tom Skipp (TS).	ven Cole	
Apolo	gies:	Other Attendees:		
Blackv	Councillors Alan Bayley, Dave vell and Jamie Huntman. CPBC illors Dick and Tucker	Sean Perry – Principal Area Transportation Co ordinator (SP), Natalie Szpigelman – ECC Highways Liaison Officer (NS), Trudie Bragg – CPBC Head o Environment (TB), Stuart Jarvis – CPBC Contracts Manager (SJ), Cheryl Salmon – Minute Taker		
Item:	Action:		Action Owner:	
1.	Welcome and Introductions:			
2.	Declarations of Interest:			
	There were none.			
3.	Minutes of meeting held on 5 th Septe	ember 2013		
	Agreed.			
	Pedestrian Crossing in Somnes Ave	enue outside Waterside Farm Sports		
		edestrians are at the crossing and this is venue. It was requested that the matter	NS	
	Highways Rangers			
	CR praised the work of the Highways happy with the way CPBC ran the serv practice model across the County.			
	Cycle Provision at Benfleet Station			
	The scheme was progressing and the hardstanding is due to be installed before the end of the current financial year. Money left over from the scheme had been used to purchase additional key fobs.			

Item:	Action:			Action Owner:			
	Parking Problems outside	e Leigh Beck	School				
	RH reported that he had undertaken a site visit at the school in the summer break. Another meeting would be held on 17 th October to meet with the local resident who had raised the issue. RH requested that Councillors Blackwell, S. Cole and Tucker and TB/SJ also attend. NS stated that this issue had been investigated previously it had been concluded that it was not feasible to install guardrail outside the school as the number of dropped kerbs in Point Road means that the guardrail will not have the desired effect.						
4.	Foksville Road j/w Furthe	rwick Road -	- Junction Improvements				
	Awaiting results of feasibility once completed.	y study. Find	ings will be reported back to the Panel				
		trians walkin	sland wanted to pay for a road safety g across the forecourt of the petrol e on 10 th October 2013.				
5.	Potential Schemes for consideration of the Panel: Minor Schemes						
	Scheme:	Estimated Cost:	Action:				
	Hadleigh Junior School		Awaiting results of speed survey and feasibility study.				
	Various Locations - Portable VAS	£4,000 (approx.)	Agreed 2 signs be purchased, 1 for Canvey Island 1 for the mainland. Investigate how easy they are to move around the Borough.				
	Speed Surveys	£2,400	Agreed speed surveys to be undertaken at 4 sites on Canvey Island and 4 sites on the mainland. Members requested to put forward sites to NS for				

Minor Schemes					
Scheme:	Estimated Cost:	Action:			
St Johns Road – 20mph zone	£20,000	Speed survey shows speeds that meet policy criteria. Agreed to progress with design			

'Amber' Bus Stop/Route Improvements Scheme

Scheme:	Estimated Cost:	Action:	
Bus Stop 150041020003, Budna Road/220 Link Road – Bus Build out	£7,500	Before progressing with the build out it was agreed that TB circulate advice received from South Essex Parking Partnership regarding the issue of cars parking in bus stops so that the Panel could consider it.	

'Green' Cycling Schemes

Location/Problem:	Estimated Cost:	Action:
Benfleet to Leigh – Missing signing and minor improvements required between Olympic Park path and station.	£50,000	Agreed to proceed with design. Panel very supportive of location and route particularly in light of additional cycling provision works at Benfleet Station.

'Amber' Cycling Schemes

Location/Problem:	Estimated Cost:	Action:	
A129, Thundersley – Lack of safe cycling routes	£200, 000	SJ to discuss suitable routes from Rayleigh to Benfleet Station with Bill Snow. Report back at next meeting.	SJ

ТΒ

	Amber' Cycling Schemes			
	Location/Problem:	Estimated Cost:	Action:	
	Canvey Island – Lack of coherent and linked cycling provision	£175, 000	Two-phased scheme to complete the east-west route and minor improvements to the sea wall route. Deferred.	
6.	Highway Rangers			
	SJ stated that the Rangers Road, Canvey Island.	s were curren	tly cutting back vegetation in Haven	
7.	Local Highways Panel Bu	dget		
	for this financial year was n available for speed surveys	early spent. s etc. It was	ras confirmed that the capital money There was some revenue money still planned that the design for schemes nd then implemented in the following	
	and enquired whether it v future. SP stated that the	vas planned Cabinet Mem Highway Ra	ork the Highway Rangers carried out to continue with the service in the ber for Highways and Transportation ngers service but it had yet to be 014/15.	
8.	AOB:			
		residents, 20mph signs on the estate ation was needed as to which roads ext Panel meeting.		
	Cornelius Vermuyden Scl	nool Road Si	gnage	
	Request from School for dir	ectional sign	in Link Road. NS to investigate cost.	NS
	Lorries Parked in Haven F	Road		
	The footpath (South of R reinstating. It was believed There was also an issue v suggested a weight restricti	SP		

highways engineers to investigate. Saints Estate, Canvey Island NS SC stated that there were problems with speeding vehicles in the area. A site inspection was requested with highway officers to assess how the problem could be addressed. NS requested to be sent relevant information regarding what the issues are. NS Link Road by Hilton Road NS SC reported there was a speeding problem in Link Road outside the Silver Jubilee Public House. It was requested with "Slow Down" signs be installed. It was suggested a site inspection be carried out. NS Solby Estate, Hadleigh NS SH requested that double yellow lines be installed. Parked cars were making it difficult for foreis and refuse vehicles to get past. Matter to be referred to the South East Essex Parking Partnership. NS Homestead Gardens, Hadleigh NS Double yellow lines have worn away. Refer to South East Essex Parking Partnership. NS Daws Heath Road/Poors Lane, Hadleigh NS Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera. A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to the Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushobotom Lane. NS stated that this was a maintena		
SC stated that there were problems with speeding vehicles in the area. A site inspection was requested with highway officers to assess how the problem could be addressed. NS requested to be sent relevant information regarding what the issues are. NS Link Road by Hilton Road SC reported there was a speeding problem in Link Road outside the Silver Jubilee Public House. It was requested that "Slow Down" signs be installed. It was suggested a site inspection be carried out. NS Solby Estate, Hadleigh NS SH requested that double yellow lines be installed. Parked cars were making it difficult for lories and refuse vehicles to get past. Matter to be referred to the South East Essex Parking Partnership. NS Homestead Gardens, Hadleigh NS Double yellow lines have worn away. Refer to South East Essex Parking Partnership. NS Daws Heath Road/Poors Lane, Hadleigh NS Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera. NS A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system.	highways engineers to investigate.	
inspection was requested with highway officers to assess how the problem could be addressed. NS requested to be sent relevant information regarding what the issues are.Link Road by Hilton RoadSC reported there was a speeding problem in Link Road outside the Silver Jubilee Public House. It was requested that "Slow Down" signs be installed. It was suggested a site inspection be carried out.NSSolby Estate, Hadleigh SH requested that double yellow lines be installed. Parked cars were making it difficult for lorries and refuse vehicles to get past. Matter to be referred to the South East Essex Parking Partnership.NSHomestead Gardens, Hadleigh Double yellow lines have worn away. Refer to South East Essex Parking Partnership.NSDaws Heath Road/Poors Lane, Hadleigh Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera.NSA129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout.White Lines – Various Roads S H reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system.Date of next meeting	Saints Estate, Canvey Island	
SC reported there was a speeding problem in Link Road outside the Silver Jubilee Public House. It was requested that "Slow Down" signs be installed. It was suggested a site inspection be carried out.NSSolby Estate, Hadleigh SH requested that double yellow lines be installed. Parked cars were making it difficult for lorries and refuse vehicles to get past. Matter to be referred to the South East Essex Parking Partnership.NSHomestead Gardens, Hadleigh Double yellow lines have worn away. Refer to South East Essex Parking Partnership.NSDaws Heath Road/Poors Lane, Hadleigh Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera.NSA129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout.White Lines - Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system.Date of next meeting	inspection was requested with highway officers to assess how the problem could be addressed. NS requested to be sent relevant information regarding	NS
Jubilee Public House. It was requested that "Slow Down" signs be installed. It was suggested a site inspection be carried out. Solby Estate, Hadleigh NS SH requested that double yellow lines be installed. Parked cars were making it difficult for lorries and refuse vehicles to get past. Matter to be referred to the South East Essex Parking Partnership. NS Homestead Gardens, Hadleigh NS Double yellow lines have worn away. Refer to South East Essex Parking Partnership. NS Daws Heath Road/Poors Lane, Hadleigh NS Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera. NS A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquires system. Date of next meeting Date of next meeting	Link Road by Hilton Road	
SH requested that double yellow lines be installed. Parked cars were making it difficult for lorries and refuse vehicles to get past. Matter to be referred to the South East Essex Parking Partnership.NSHomestead Gardens, Hadleigh Double yellow lines have worn away. Refer to South East Essex Parking Partnership.NSDaws Heath Road/Poors Lane, Hadleigh Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera.SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout.White Lines - Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system.Date of next meetingLite of next meeting	Jubilee Public House. It was requested that "Slow Down" signs be installed.	NS
SH requested that double yellow lines be installed. Parked cars were making it difficult for lorries and refuse vehicles to get past. Matter to be referred to the South East Essex Parking Partnership. NS Homestead Gardens, Hadleigh NS Double yellow lines have worn away. Refer to South East Essex Parking Partnership. NS Daws Heath Road/Poors Lane, Hadleigh Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera. A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting Date of next meeting	Solby Estate, Hadleigh	NG
Double yellow lines have worn away. Refer to South East Essex Parking Partnership. Daws Heath Road/Poors Lane, Hadleigh Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera. A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting	it difficult for lorries and refuse vehicles to get past. Matter to be referred to	NS
Partnership. Daws Heath Road/Poors Lane, Hadleigh Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera. A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting	Homestead Gardens, Hadleigh	NS
 Problem with speeding vehicles. It was suggested it was an ideal site for a 20mph camera. A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting 		
20mph camera. A129 Rayleigh Road SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting	Daws Heath Road/Poors Lane, Hadleigh	
 SH enquired whether the plan to re-align the white lines on the approach to Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout. White Lines – Various Roads SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting 		
Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the roundabout.White Lines – Various RoadsSH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system.Date of next meeting	A129 Rayleigh Road	
SH reported that the white lines at junctions were wearing out on a number of roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting	Rayleigh Weir was going ahead. Currently the road layout was causing problems as it resulted in drivers changing lanes on approach to the	
roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member enquiries system. Date of next meeting	White Lines – Various Roads	
	roads including Manor Road and Rushbottom Lane. NS stated that this was a maintenance issue. SH to refer list of roads to ECC through Member	
Thursday 28 th November 2013 at 3pm	Date of next meeting	
	Thursday 28 th November 2013 at 3pm	

Capital Highway Improvements Programme

		ID	District	Location	Scheme	Problem	Justification / Comments	Requested By	Estimated Cost (£)	Estimated Timescale Assuming smooth progress	RAG	Recommende d by LHP	Approved by Cabinet member
5	CF	P7	Castle Point	Foksville Road j/w Furtherwick Road, Canvey	Junction Improvements	Large vehicles are unable to safely manouvre the junction.	Awaiting results of feasibility study.	LHP			Green		
18	CF	P20		Hadleigh Junior School			Awaiting results of speed survey and feasibility	Cllr Reeves/Cllr Hart			Green		
20	CF	P22	Castle Point	Various	Portable VAS	Request from LHP for possible portable VAS to be circulated round Castle Point Borough.	Speed surveys agreed by LHP. Locations for speed surveys are currently being agreed. Once the speed surveys have been carried out then we can ascertain which locations meet criteria for installation. We will then also hold a meeting with CPBC Rangers service to ascertain what is involved in rotating these VAS to see if the Rangers can undertake this service.	Clir Hart	£250 per speed survey, approx. £2000 per VAS.				

	ID	District	Location	Scheme	Problem	Justification / Comments	Requested By Estimated Cost (£)	Estimated Timescale Assuming smooth progress	RAG	Recommende d by LHP	Approved by Cabinet member
24	LCAS132018	Castle Point	Point Road, Canvey	Install two bollards by pram crossing on grass verge opposite Leigh Beck School in order to stop cars mounting the kerb.	Inconsiderate parent parking during school drop off and pick up times.	School has requested guardrail/fencing for several years but due to number of dropped kerbs at this location it would not have the desired effect and the result has therefore been turned down by Engineers. Following a further site visit at the school, it was agreed that we would investigate installing two bollards at the pram crossings at either end of the large grass verge opposite the school in order to stop parents mounting the kerb and parking on the verge. Following validation by Essex Highways Engineers, it was decided that installing these bollards may prevent vehicles from driving up on the pram crossings, it may not deter them from parking on the grass verges as they can mount the kerb. The only possible solution to the issues at this location would be to install trief kerbs, but this will be a costly scheme.	Cllr Blackwell and Cllr Howard		Red		
22	LCAS132019	Castle Point	Haven Road, Canvey	HGV directional signage	There have been complaints about HGVs accessing Charfleets Industrial Estate via Haven Road rather than using Roscommon Way. Roscommon Way was built with the intention of directing traffic along this route to the industrial estate. It has been requested by the Transport Planning Team that we look at black and white directional signage to direct HGVs and other traffic to the industrial estate via Roscommon Way to alleviate the heavy traffic flow that carries on along Canvey Road and then onto Haven Road.	The Transport Planning Team has stated that it would be best to wait until the link road at Oikos has been created before installing this directional signage as it may direct some vehicles the wrong way. Tony Butson to provide update at LHP meeting on 28th November.	Transport Planning Team		Amber		

	ID	District	Location	Scheme	Problem	Justification / Comments	Requested By	, Estimated Cost (£)	Estimated Timescale Assuming smooth progress	RAG	Recommende d by LHP	Approved by Cabinet member
23	LCAS132020	Castle Point	Haven Road, Canvey	Weight limit	Haven Road. A 7.51 weight limit has been request along Haven Road from the Oikos building to the Lobster Smack to prevent	Possible clearway requested, however this matter would need to be referred to SEPP. With regards to the weight limit, a study was undertaken and it was suggested that a weight limit may not be efficient at this location. TB to explain at meeting on 28th November.	Cllr Howard			Amber		
			KEY									

Green	A high priority scheme against strategic criteria
Amber	A low priority scheme against strategic criteria
Red	A scheme which is against Essex Policy or there is no appropriate engineering solution.
	Scheme pending validation



Scheme Update

Somnes Avenue Pedestrian Crossing Upgrade

The Castle Point Local Highways Panel allocated £138,000 of funding to upgrade the existing zebra crossing on Somnes Avenue to a signalised puffin crossing.

The consultation is currently underway and is due to conclude on the 22nd November. At the time of writing this report there had been no formal objections to the proposal.

If there are no objections then it is hoped that this crossing will be installed by the end of the 2013-14 financial year. If objections are received then a Cabinet Member Action report will need to be completed and due process followed to ensure that all objections are taken into consideration and responded to.



Reproduced from the Ordnance Survey mapping with the permission of the Controller of Her Majesty's Stationery Office © Crown copyright. Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings. Essex County Council Licence No. 100019602. 2004. Drawing - X:\Design Consultancy\Capital Programme\DC Scheme Files 2012-13\DC1398 - Kents Hill Road North VAS\3 - Drawing Records\DC1398 template.dwg. Layout - A2. Plotted Monday 21 October 2013 - 12:02 by shaun.morgan





Scheme Update

Ferry Road- Benfleet Station Cycle Storage

Castle Point Local Highways Panel approved £30,000 to install a new cycle storage unit at Benfleet Station. In order to install the unit we needed to connect a new power supply and create a hardstand for the shelter to sit on.

Example images of the compound are presented below:





The cost of the cycle storage unit with mag locks, lighting and mesh at the bottom (to deter people gaining access under the bottom of the compound) is $\pounds 16,266.00$. We have also ordered more key fobs for the existing compound at a cost of $\pounds 1117.00$. These costs will be added to the cost for the hardstand and electricity connection.

Works on the hardstand have begun on the 18th November 2013 with a view for completion within a week. Therefore, the hardstand should be in place by the date of the next Castle Point LHP on 28th November. The unit has been ordered and will be in place before the end of the current financial year.



Sainsburys, Canvey Island

Road Safety Improvements

Sainsburys on Canvey Island have put forward some road safety proposals that are currently being considered by Essex County council.

The suggested improvements are to install guardrail along the footway by the petrol garage in order to direct pedestrians along the footway so that they do not cut through the petrol forecourt causing conflict with vehicles. They are also hoping to install guardrail along the footway by the access road so that pedestrians are guided from the safe crossing point rather than cutting across the road.

Other suggested measures are to place hatching on the carriageway on the access road to narrow the width so that vehicles entering the access road do not cut across the exit lane into Foksville Road. They would also like to improve the existing crossing point by installing new kerbing and tactile paving.

This matter has now been passed to the Development Management Team to progress. The maintenance liabilities will need to be discussed and if the scheme is able to progress, Sainsburys will be provided with a permit to work on the highway.



Castle Point Borough Council Highways Rangers

Report to the Local Highways Panel 28th November 2013

The Highway Rangers, Len and Tony, continue to undertake improvement works throughout the Borough both routine maintenance on the main artery roads through the Borough and specific areas as reported by inspectors and residents.

In a review of the way we work we noted that some of the vegetation removal was labour intensive and not being done in an efficient manner, as a result we have purchased petrol powered hedge trimmer, strimmer with bush cutter and blowers. These pieces of equipment have improved our output.

We are also exploring the possibility of placing the Highway Rangers on a weed spraying course so that they will be able to spray areas of the public highway that Essex Highways weed spraying process does not appear to touch, alleyways and around street furniture, again this is being investigated to improve output.

During the recent high winds the Highway Rangers inspected the main artery routes removing fallen branches and displaced vegetation.

Going forward the continuation of the current Essex Highways order for the Highway Rangers beyond its finish date is essential to continue the excellent works undertaken in this first year.

Following are some photos of the works undertaken.

Stuart Jarvis MinstLM

Contracts Manager

Castle Point Borough Council













