

Head Office

3B HAIGH PARK ROAD
STOURTON, LEEDS
LS10 1RT

T: 0113 2775360

E: info@centuriontraffic.com
W: www.centuriontraffic.com

Location:

Henham FP32 Elsenham Emergency
Hut NR crossing

Date:

22/09/2017

Drawing Reference:

22-09-17-51

Drawn by:

MS

Drawing Size:

A3

Scale:

NTS



Notes

- All temporary traffic management shall be in accordance with Chapter 8 of the Traffic Signs Manual 2009.
- All temporary traffic management shall be in accordance with the Traffic Signs Regulations and General Directions 2002.
- All temporary traffic management shall conform to the Safety at Street Works and Road Works - A Code of Practice 1991.
- All temporary traffic management signs should be located 450mm minimum from the kerb face.
- All temporary traffic management sign locations are indicative and are subject to on site approval from the Engineer.

