BRAINTREE DISTRICT LOCAL HIGHWAYS PANEL



THIS MEETING IS OPEN TO THE PUBLIC http://www.braintree.gov.uk/meetings

AGENDA

Date: Thursday 4th July 2013

Time: 6.00pm

Venue: Committee Room 1, Causeway House, Braintree, CM7 9HB

Membership:-

Essex County Council	Braintree District Council	Braintree Assoc of Local Councils
Councillor D Louis	Councillor J Abbott	Councillor J Bendall
Councillor Lady Newton	Councillor M Banthorpe	Councillor J Clark
Councillor J Pike	Councillor M Lager	Councillor M Fincken
Councillor R Walters	Councillor R Mitchell	Councillor A Hayward

- 1. Appointment of Chairman and Vice-Chairman of the Panel
- 2. Apologies for Absence
- 3. Declarations of Interests. To declare the existence of any interests relating to items on the Agenda having regard to the Code of Conduct for Members and having taken appropriate advice (where necessary) before the meeting.
- 4. **Minutes**. To approve as a correct record the Minutes of the meeting of the Braintree District Local Highways Panel held on 14th March 2013 (copy previously circulated).
- 5. **Matters Arising**. To consider matters arising from the Minutes which are not covered on the Agenda.
- 6. Question Time. (See paragraph on Page (ii) of the Agenda)
- 7. **Casualty Reduction Schemes**. To consider four schemes. (Reports attached) (Pages 1, 6, 11 and 16)
- Schemes for Consideration by the Panel. To consider a schedule of schemes and to determine those which should be approved and whether any historic schemes may be deleted (copy attached) (Green and Amber Rating – Page 21) (Red Rating – Page 30)





- Schemes Already Recommended for Approval. To receive an update.
 - (1) Schemes recommended for approval (copy attached) (Page 32)
 - (2) Schemes recommended for approval which have also been programmed (copy attached) (Page 45)
- 10. To consider any other items which the Chairman has decided are urgent.
- 11. **Dates for Meetings of the Panel**. To note the following dates of forthcoming meetings of Braintree District Local Highways Panel and to determine whether the January meeting should be delayed until either 23rd January 2014 or 30th January 2014:-

3rd October 2013 16th January 2014 (possible change to 23rd January 2014 or 30th January 2014) 3rd April 2014

QUESTION TIME

Immediately after the Minutes of the previous meeting have been approved there will be a period of up to 30 minutes when members of the public can speak for up to three minutes each on items on the Agenda. Members of the public wishing to speak should contact the Council's Member Services Section on 01376 552525 or e-mail alison.webb@braintree.gov.uk at least two working days prior to the meeting. Members of the public can remain to observe the whole of the public part of the meeting.

Health and Safety

Any persons attending meetings at Causeway House are requested to take a few moments to familiarise themselves with the nearest available fire exit, indicated by the fire evacuation signs. In the event of a continuous alarm sounding during the meeting, you must evacuate the building immediately and follow all instructions provided by a Council officer who will identify him/herself should the alarm sound. You will be assisted to the nearest designated assembly point until it is safe to return to the building.

If you require any further information relating to this Agenda, or wish to forward your apologies for absence, please contact Alison Webb on 01376 552525 or email alison.webb@braintree.gov.uk

A PEACE Member Services Manager

(The last page of this Agenda is numbered 48)

(ii)


A _F			
1			

EEC Casualty Reduction Site Investigation 2013/14

Location: Kings Lane J/w A120, Braintree Investigation Period: 01/06/2007 to 31/05/2012

District: Braintres Grid Reference: 578,350 223,480

1.0 Site Location Plan




2.0 Site Description

Kings Lane is a local distributor road that links the A120 from Braintree to the village of Stisted. The A120 is a single carriageway trunk road managed by the Highways Agency. They form a T junction and are derestricted (60mph) and are not street lit. There are footways along both sides of the A120, there are none along Kings Lane due to its rural nature.

3.0 Personal Injury Collision Analysis (see AccsMap Data & attached stick diagrams)

A study of the Personal Injury Collision data for the period from 01/06/2007 to 31/05/2012 at this location shows that there have been 5 Personal Injury Collisions, 2 of them serious and 3 of them slight resulting in 2 serious and 4 slight casualties. Four collisions involved vehicles exiting Kings Lane failing to give way to traffic travelling eastbound along the A120. The other collision occurred when vehicles on the A120 allowed a vehicle to exit from Kings Lane and an eastbound motorcyclist overtook the vehicles giving way and hit the car joining the A120. One collision occurred during the hours of darkness and two occurred in wet conditions.

COLLISION HISTORY UPDATE (31/05/2012 – 31/01/2013): There has been one further Slight injury collision on 17/08/2012 resulting in two casualties which also involved a vehicle failing to give way when exiting Kings Lane and hitting an eastbound vehicle on the A120.



4.0 Site Observations and Photographs

The approach to the A120 along Kings Lane is straight however the road curves to the left at the junction which restricts the advanced visibility of the give way sign (see Photograph 1). The give way sign at the junction is dirty (see Photograph 2) and due to its location and the position of a telegraph pole and stay wire it does not stand out as you approach. There are give way lines, central hatching and a triangle; however these are faded and need renewing. The visibility when exiting Kings Lane is reasonable in both directions, however due to the high volume of traffic on the A120 it is likely that vehicles may take risks when joining the A120. There are signs on both approaches along the A120 to warn of the Kings Lane junction.



Photograph 1: View travelling southbound along Kings Lane towards the junction with the A120.



Photograph 2: Kings Lane at its junction with the A120.

5.0 Recommendations

Following the site inspection and an analysis of the previous Personal Injury Collisions, it is recommended that the following measures are undertaken:

- i) Replace the existing give way sign on Kings Lane on a yellow backing board. Relocate the sign if possible so that it is more visible for approaching motorists.
- ii) Renew the existing white give way lines, central hatching and triangle at the junction.
- jii) Install new advanced give way sign on Kings Lane with distance sub-plate.

6.0 Economic Analysis

First Year Rate of Return (FYRR) Calculation

% FYRR = Annual Accident Savings x 100

Scheme Cost Assumptions: Average annual accident cost (£) £104,720.00 (TAG 3.4.1 Aug 2012) Accidents treated Casualties treated Investigation time period (years) Estimated cost of recommended remedial measures (including Design, Audit and Traffic Management) £500 00 1) Install yellow backed give way sign £1,000.00 2) Renew give way lining 3) Install new advanced give way sign £500.00 4) Design, project management & Safety Audit. £750.00 £2.750.00 10 Rospa Accident saving produced by proposed treatment (%) %FYRR 381 Number of accidents that would not have occurred had the remedial actions been implemented at the start of the three-year accident period 0.5 or 0.10 each year Number of casualties that would not have occurred had the remedial actions been implemented at the start of the three-year accident period or 0.12 each year


Approvals			
Name/role	Tel No.	Signature	Date
Safety Engineer: Jenny Hill	01245 437253		
Safety Engineering Manager: Nicola Fos	ster		
Discussed/Agreed with Area Contact			
Name/role	Tel No.	Signature	Date
Financial Authorisation Code	Date of Authori	sation	
Contacts			
Name/role	Address and/or	Tel No.	
Essex Police Representative: Trevor Stubbington			
County Councillor:		-	
Other:			

,	

ECC Casualty Reduction Sits Investigation 2013/14

Location: 4131 Notley Green Roundabout, Great Notley - District: Braintree investigation Period: 01/01/2007 to 31/05/2012 - Grid Reference: 573,973 219,840

1.0 Site Location Plan



2.0 Site Description


The A131 runs between Braintree and Chelmsford. The Great Leighs Bypass is a derestricted (70mph) section of dual carriageway that links the Moulsham Hall Roundabout with the Notley Green Roundabout. The Notley Green Roundabout is street-lit and there are no footways due to its rural location. It is deresticted but the speed limit drops to 60mph as you leave the roundabout on the section that bypasses Great Notley.

3.0 Personal Injury Collision Analysis (see AccsMap Data & attached stick diagrams)

A study of the Personal Injury Collision data for the period from 01/06/2007 to 31/05/2012 at this location shows that there have been 8 Personal Injury Collisions (one of them serious) resulting in one serious and 7 slight casualties. Two collisions involved vehicles in the right hand northbound A131 approach lane turning left to continue on the A131 and hitting vehicles that were intending to go straight ahead (one of them a motorcycle). On the A131 south eastbound approach to the roundabout one collision involved a vehicle in the right hand lane turning left into London Road and hitting a cyclist intending to continue over the roundabout. There was also a failure to give way on this approach where a vehicle struck a cyclist on the roundabout. Three collisions involved single vehicle loss of controls (two of them motorcyclists) and occurred on different arms of the roundabout. The other collision

involved a vehicle turning right on the roundabout from London Road cutting across the path of a motorcyclist. One collision occurred during the hours of darkness and one occurred on a wet/damp road surface. Five collisions involved motorcyclists and two involved cyclists.

COLLISION HISTORY UPDATE (31/05/2012 – 31/01/2013): There has been one further Serious injury collision on 22/09/2012 involving a motorcyclist turning left from the Great Leighs Bypass to continue on the A131 and striking a vehicle intending to go straight over the roundabout into London Road.



4.0 Site Observations and Photographs

Both A131 approaches to the Notley Green roundabout have good forward visibility (see Photographs 1 & 2) and advanced directional signs indicating the route of the A131. To continue on the A131 on either approach is not the 'straight ahead' movement motorists may expect given the continuation of the main A131 route. This may be the reason for some of the collisions involving left turners in the right hand lane on the northbound approach to the roundabout if they have not seen the ADS sign. It may also be that drivers who drive this journey on a regular basis ignore the ADS but know that the entry and exit of the roundabout in both directions is two lanes wide and therefore don't worry about moving into the correct lane.



Photograph 1: A131 northbound approach to the Notley Green Roundabout.



Photograph 2: A131 south eastbound approach to the Notley Green Roundabout.

5.0 Recommendations

Following the site inspection and an analysis of the previous Personal Injury Collisions, it is recommended that the following measures are undertaken:

- i) Install lane directional arrows on both approach lanes of both A131 approaches to the roundabout to highlight that left turners should take the left hand lane.
- ii) Renew the existing circulatory carriageway markings.

6.0 Economic Analysis

First Year Rate of Return (FYRR) Calculation

% FYRR = Annual Accident Savings x 100 Scheme Cost Assumptions: £104,720 00 (TAG 3 4 1 Aug 2012) Average annual accident cost (£) Accidents treated Casualties treated Investigation time period (years) Estimated cost of recommended remedial measures (including Design, Audit and Traffic Management) £3,000.00 1) Install lane markings on both A131 approaches 2) Renew circulatory carriageway markings £2,000.00 3) Design. project management & Safety Audit £1,000.00 26.000.00 Accident saving produced by proposed treatment (%) 34 Rospa

%FYRR 475

Number of accidents that would not have occurred had the remedial actions been implemented at the start of the three-year accident period

1.36

0.27 each year

Number of casualties that would not have occurred had the remedial actions been implemented at the start of the three-year accident period

1.7

or 0.34 each year

Approvals			
Name/role	Tel No.	Signature	Date
Safety Engineer: Jenny Hill	01245 437253		
Safety Engineering Manager: Nicola Foster			_
Discussed/Agreed with Area Contact			1111
Name/role	Tel No.	Signature	Date
Financial Authorisation Code	Date of Authori	sation	
Contacts			
Name/role	Address and/or	Tel No.	
Essex Police Representative: Trevor Stubbington			
County Councillor:			
Other:			

	,	
7/2		

ECC Casualty Reduction Site Investigation 2013/14

Location: A131 Mount Hill I/w White Horse Avenue, Halstead District: Braintree Investigation Period: 01/06/2007 to 31/05/2012 Grid Reference: 580,600 229,924

1.0 Site Location Plan




2.0 Site Description

Mount Hill is part of the A131 which runs between Braintree and Halstead. As you enter Halstead the speed limit changes from derestricted to 30mph at the junction of the A131 and Oak Road. The junction of White Horse Avenue and the A131 is 120m within the 30mph limit. The road is street-lit from the start of the 30mph limit and there is a footway on the south side of the road.

3.0 Personal Injury Collision Analysis (see AccsMap Data & attached stick diagrams)

A study of the Personal Injury Collision data for the period from 01/06/2007 to 31/05/2012 at this location shows that there have been 4 Slight Personal Injury Collisions, resulting in five slight casualties. All four collisions involved vehicles turning right from the A131 into White Horse Avenue being shunted by from behind. One collision involved alcohol. No collisions occurred during the hours of darkness and three occurred in wet/damp road surface.



4.0 Site Observations and Photographs

The advanced view of the junction of White Horse Avenue when travelling northbound on the A131 is reasonable (see Photograph 1), however there is no warning of the junction. The road curves to the left slightly prior to the junction; however any vehicles waiting to turn right can still be seen waiting by approaching traffic. The start of the 30mph limit is well signed with yellow backed roundels that can be seen in advance (see photograph 2).



Photograph 1: A131 Mount Hill, travelling northbound towards the junction with White Horse Avenue (on the offside).



Photograph 2: A131 travelling northbound at the junction with Oak Road.

Recommendations

Following the site inspection and an analysis of the previous Personal Injury Collisions, it is recommended that the following measures are undertaken:

- i) Install new junction ahead warning sign on the northbound approach to White Horse Avenue with accompanying 'SLOW' marking.
- ii) Install 30mph speed roundel at the 30mph gateway.
- iii) Clean the 30mph gateway signs and the advanced junction warning sign for Oak Road.
- iv) Cut back the existing vegetation on the north side of the A131 east of the access into Blamsters Farm to the highway boundary.

6.0 Economic Analysis

First Year Rate of Return (FYRR) Calculation

% FYRR = Annual Accident Savings x 100 Scheme Cost Assumptions: Average annual accident cost (£) Accidents treated

Casualties treated Investigation time period (years) Estimated cost of recommended remedial measures

(Including Design, Audit and Traffic Management)

- 1) Install junction warning sign
- 2) Install 2No SLOW markings & 30 roundel
- 3) Clean existing signs 4) Cut back vegetation
- 5) Design, project management & Safety Audit

£300.00 2600 00 £200.00 £650 00 £750 00 £2,500.00

Accident saving produced by proposed treatment (%)

10 Rospa

£104,720.00 (TAG 3.4.1 Aug 2012)

%FYRR 251

Number of accidents that would not have occurred had the remedial actions been implemented at the start of the three-year accident period

0.3

or 0.06 each year

Number of casualties that would not have occurred had the remedial actions been implemented at the start of the three-year accident period

0.4

0.08 each year

Approvals			
Name/role	Tel No.	Signature	Date
Safety Engineer: Jenny Hill	01245 437253		
Safety Engineering Manager: Nicola Foster			-
Discussed/Agreed with Area Contact			
Name/role	Tel No.	Signature	Date
Financial Authorisation Code	Date of Authori	sation	
Contacts			
Name/role	Address and/or	Tel No.	<u></u>
Essex Police Representative: Trevor Stubbington			- 2
County Councillor:			-
Other:			See
Comments			


	na)		

ECC Casualty Reduction Site Investigation 2013/14

Location: A131 Sudbury Road, Carley Cross, Halstead nvestigation Period: 01/01/2009 to 31/05/2012

District: Braintree Grid Reference: 584098, 235,206

1.0 Site Location Plan




2.0 Site Description

Sudbury Road is part of the A131 which runs between Sudbury and Halstead. The road is derestricted (60mph). There are various bends along this route and some have previously been treated with improved signage and red road surface bands. There is no signing or lining to highlight this particular bend. The road is not street-lit due to its rural location and there are no footways.

3.0 Personal Injury Collision Analysis (see AccsMap Data & attached stick diagrams)

A study of the Personal Injury Collision data for the period from 01/06/2009 to 31/05/2012 at this location shows that there have been three Personal Injury Collisions, one of them serious resulting in one serious and four slight casualties. All three collisions involved vehicles travelling southbound losing control on the left hand bend located 250m south of the junction of Park Road (by Catley Cross Farm). Two of these were single motorcycle collisions. The other collision involved a car losing control and hitting another oncoming car. Two collisions occurred during the hours of darkness and two occurred on a wet/damp road surface (one of them related to ice/drainage issues).



4.0 Site Observations and Photographs

The advanced view of the left hand bend travelling southbound on the A131 is good (see Photograph 1), however there is no warning of the bend and it is not highlighted (see Photograph 2) and due to the rural nature of the road the bend doesn't stand out. Also because most of the bends along this route have warning measures motorists may not expect this bend as it's not highlighted.



Photograph 1: A131 Sudbury Road, travelling southbound towards Halstead approaching the left hand bend.



Photograph 2: A131 Sudbury Road, looking northbound at 'S' bend.

5.0 Recommendations

Following the site inspection and an analysis of the previous Personal Injury Collisions, it is recommended that the following measures are undertaken:

- i) Install new S bend ahead warning sign with Max Speed 30 sub-plate (to be yellow backed) on the southbound approach to the left hand bend with accompanying 'SLOW' markings.
- ii) Install yellow backed chevron sign on the bend.
- iii) Install reflector posts around the 's' bend (Where You Look Is Where You Go, WYLIWIG treatment).
- iv) Check and clear the drainage system to ensure that there is no ponding on the carriageway.
- v) Renew all existing white lining for 100m on both approaches to the 's' bend and throughout it.

6.0 Economic Analysis

First Year Rate of Return (FYRR) Calculation

% FYRR ≈ Annual Accident Savings x 100
Scheme Cost

Assumptions: £104,720.00 (TAG 3.4.1 Aug 2012) Average annual accident cost (£) Accidents treated Casualties treated Investigation time period (years) Estimated cost of recommended remedial measures (including Design, Audit and Traffic Management) £500.00 1) Install junction warning sign & chevron sign 2) Install new SLOW marking & renew existing white lining 21,000 00 3) Install reflector posts £4.000.00 £1,000.00 4) Check and clear drainage system. £1,000 00 5) Design, project management & Safety Audit £7,500.00 Accident saving produced by proposed treatment (%) 20 Rospa

%FYRR 279

Number of accidents that would not have occurred had the remedial actions been implemented at the start of the three-year accident period

0.6 or 0.20 each year

Number of casualties that would not have occurred had the remedial actions been implemented at the start of the three-year accident period

or 0.33 each year

Approvals		(Table 1971	
Name/role	Tel No.	Signature	Date
Senior Engineer: Jenny Hill	01245 437253		
Safety Engineering Manager: Nicola Foster			-
Discussed/Agreed with Area Contact			
Name/role	Tel No.	Signature	Date
Name/role	Date of Authori	Total Of the American A	
Contacts Name/role	Address and/or	Tel No	
Essex Police Representative: Trevor Stubbington			
County Councillor:			
Other:			
Comments			

	127	
	243.	

ID	origin date Location	Scheme	Problem	Justification / Comments	Requested By	Estimated Cost (E)	RAG
i,BRA6 1 4	Nov-12 Grove Rd, Witham	altering the footway	high slope at crossing	The pitch of the slope means residents on mobility scooters find hard to negotiate. Is not an easy fix and therefore a survey should be carried out to ascertain levels and stats in the vicinity. A design can therefore be conducted to re-profile the crossing point.	Witham Town Council	£17,000) amber
BRA9 2 1	Sep-12 Liston Lane, Liston	20 M PH speed limit	Narrowness of the lane through Liston and speed some vehciles travel	average speed measured each day in both directions (over two weeks) was on average 26-27 MPH with with a high of 28.6 and low of 23.5. 20mph limit/zone would require repeater signs every 200m. The terminal signs would need illumination and would require an electricity supply to be provided at each entry to the 20mph limit (3no locations). There would also be potential future maintenance. It should be noted that police activity to enforce such a limit will be unlikely unless there is a significant excessive speeding issue. It should also be noted that physical traffic calming measures will not be installed as part of a 20mph limit.		£20,000	amber
BRA4 3-1	Dec-12 ChippingDell, Witham	At end and facing uphill erect short length of fencing with reflective panel to alert drivers to bend	Vehicles travelling down hill at end of Chipping Dell towards river Walk and in icy conditions failing to stop.	It is recommended that a highway boundary check be carried out to ensure that the structure would be on Highway,	Clir Lager	£5,000	amber
BRA3 4.5	Nov-12 Cressing Road, Witham	moving the guardrail from it's present position to the edge of the footway and re-laying the edging to make this section a pathway at the rough area of land where a tree has been removed.	inadequate calming, barrier, together with section of unmade-up pathway where tree has been removed	Cost including Design and Supervision.	Cllr Lager	£10,000	Amber

Improvement Schemes - For Consideration

ID	origin dats	· Location	Scheme	Problem	Justification / Comments	Requested By	Estimated Cost (£)	RAG
5 IT021	Former	Church Road, Hatfield Peverel, Ranulph Way to Church	Footway		Currently walkable verge - Need highway boundary confirmed, possible common land issue. Land investigation required if panel want to proceed	Reserve List	£20,000 (+ lland)	Amber
6 IT016	Former LHP (2009)	B1019 from Wickham Bishops Road to Ulting Road Hatfield Peverel - Southern side of carriageway	'Widen existing footway	Narrow footway.	B1019 previously investigated by major schemes. A footway already exists, use of the footway is limited due to remoteness - the carriageway is narrow at this location, would be necessary to widen onto verge - non highways. Estimate of scheme appears light. Land issues; engineering issues. Scheme unlikely to be cost effective.	From reserve list 1	£200,000	Amber
24	Historic - Origin Unknown	The Grove J/w Newland St, Witham.	Dedicated Right Turn lane at signals	Congestion	There is a fibre optic BT cable which will require diversion, this will require significant funds \$106 funding will require a substantial top-up (£112k expires in 2021).	Historic - Origin Unknown	£200,000	Amber
8 IT019		Bures, Colchester Road; Colchester Road, Bures, from Millennium Footbridge to link up with O/S Boat House; Colchester Road, Bures O/S number 44 and Public Right Of Way 77		Narrow footway / no crossing	Alternative route on opposite side of road. Carriageway narrow at this point. Suggest should ensure there's an effective dropped crossing. Suggest that a controlled crossing would not be appropriate - it would urbanise the area and there is unlikely to be the pedestrian volumes. Note - this scheme is on the 2011/12 scheme list for advance design. Against Policy - on the Strategic Route Network	From Reserve List 11 and 39	£135,000) amber
	Origin	Cressing Road vicinity of Beckers Green Road and Stubbs Road	Zebra crossing	Difficult to cross road	PV2 required. Already children crossing sign in place. PR2 Road. Against policy	Historic - Origin Unknown	£135,000) amber
1	Historic - Origin Unknown	High Street, Kelvedon between number 33 and Labour Club	Central crossing island	Difficult to cross road	If an island is provided it may require removal of parking. Build-out? PR2 Road. Against policy	Historic - Origin Unknown	£20.000) amber

ID	origin dal	te Location	Scheme	Problem	Justification / Comments		Estimated RAG Cost (E)
11 IT85	Former 8 LHP	Boars Tye Road, Silver End	Zebra Crossing	Difficult to cross road	On strategic network, against policy. Precedent for zebra crossings in vicinity. PV2 survey required	From Reserve List	£65,000 amber
12 IT02	Former 4 LHP	Coldnailhurst Avenue junction	New Roundabout	Unclear problem, more information required	New mini-roundabout? Is this appropriate/cost effective for the flows on Queens Road? Suggest traffic count may be required. No collisions at site	Reserve list 26	£65,000 amber
13 IT854	Former	Boars Tye Road, Silver End	Footway Extension (Ralph's Farm to Brettons 400m)	Pedestrian safety	It would be difficult for the path to go along in front of the group of dwellings as it would involve private land issues and also would mean losing parts of walls, drives and hedges - Building the path from where it ends now out to the first house (so only using highway verge) estimate to be approx 200m could be completed and response from residents was overwhelmingly positive, it would help with walking for recreation, walking dogs, getting to the shops, doctors, work. the residents at the first house of the detached group in Boars Tye Roadthere are willing to offer a strip of land for free to assist the process.	From Reserve List	£60,000 amber
14	Jun-13	Village Green in White Colne	installation of titan kerbs	continual damage caused by vehicles	The Parish Council would like the installation of titan kerbs to be considered in the part of the top corner of the Village Green that was discussed at a site meeting.	White Colne Parish Council	£5,000
15	Jun-13	The street Hatfield peverel, near hatfield square	upgrade of Zebra Crossing to Pelican	visibility and safety concerns		Hatfield Peverel Parish Council	£140,000

ID	origin date	Location	Scheme	Problem	Justification / Comments	Deminstal Bu	Estimated Cost (£)	RAG
16	Jun-13	The street Hatfield peverel, near the mini market	upgrade of Zebra Crossing to Pelican	visibility and safety concerns		Hatfield Peverel Parish _Council	£140,000	amber
17	Jun-13	Maldon Road, Hatfield Peverel	upgrade of Zebra Crossing to Pelican	visibility and safety concerns		Hatfield Peverel Parish Council	£140,000	amber
BRA9		Henny Back Road and Moat Lane, Alphamstone	unsuitable for HGV Sign	Heavy traffic, sat nav - damage to the banks	This may not resolve the problem depeding on what route the vehcile needs to take	Alphamston e & Lamarsh Parish Council	£1,000	ambe

KEY

Green	A high priority scheme
Amber	A medium priority scheme
Red	A scheme which is against Essex Policy or there is no appropriate engineering solution.

Total Cost £1,358,000

	ID	originatin g date	Location	Scheme	Other issues / comments	Requested By	Estimated Cost	RAG
1	BRA79	Oct-11	Lyons Hall Road, Braintree	Horse and rider signs	Site inspecttion noted lack of signage.	Braintree Equestrian Centre Limited	£1,000	amber
2	LBRA132035	May-13	Lucking Street, Toldishall Road and Church Street , Great Maplestead	Three speed surveys for valdiation of the extension of the 30-mph speed limit		Great Maplestead Parish Council	£630	amber
3	LBRA132036	Jun-13	Bower Hall Drive from Bendyshe Court to the Doctor's Surgery	speed ssurvey for 20mph speed limit		Steeple Bumpstead Pansh Council	£210	amber
4	LBRA132030	Jun-13	Avenue Road Witham	PV2 survey for zebra crossing	New companny in area with 600 people needing to cross to station	Witham Town Council	£890	amber
5	LBRA132031	Jun-13	St. Andrew's School, Bulmer	Three speed survey for speed limit changes		Bulmer Parish Council	£630	amber
6	LBRA132032	Jun-13	cornish hall end	Speed survey due to speeding concerns	the parish that has experienced both a fatality and numerous accidents	Finchingfield Parish Council	£210	amber
7	ULBRA132034	Jun-13	Head Street or Sudbury Road	PV2 survey for zebra crossing		Halstead Town Council	£890	amber
8	LBRA132033	Jul-13	Belchamp St. Paul, Vicarage Road	Speed survey due to speeding concerns		BELCHAMP ST PAUL & BELCHAMP OTTEN PARISH COUNCIL	£210	amber

KEY

Green	A high priority scheme
Amber	A medium priority scheme
Red	A scheme which is against Essex Policy or there is no appropriate engineering solution.

Bus Stop Improvements

origi date	inating	Location	Details of Scheme	Issues / Comments / Reason for Scheme	Scheme Origination	Approx Timescale	Estimate d Cost	Priority (RAG)
23	Jun-13	Stop ID 14004001 Prested Hall	Replace old Parish shelter with wooden shelter	Parish have requested funds to replace their old	Parish request	6 months	£8,000	Green
2	Jun-13	Stop ID 14004003 Gore	Replace old Parish shelter with wooden shelter	Parish have requested funds to replace their old metal shelter	Parish request	7 months	£8,000	Green
	Jun-13	Tye Green Post Office,	Replace old shelter with a larger model. Re-	Shelter is too small to accommodate the large inumber of passengers using this stop	Requested by local residents, & Parish Council	6 months	£10,000	Green
4	Jun-13	Stop ID 240090Y9 Queen Edith Drive Steeple Bumpstead	Install and extra large shelter suitable for school children	Parish request. There is a large Flood Defence scheme in progress at the moment funded by the Environmental Agency and the contactors will install the base whilst they are on site if the scheme is agreed.	Parish request	8 months	£12,000	Green
5	Jun-13	Stop ID 240090Y9 Queen Edith Drive Steeple Bumpstead	Install raised kerbs	The stop is used by local residents during the day.	Requested by Parish	8 months	£5,500	Green
6	Jun-13	Stop ID 24009009	Formalise bus stop with ECC Pole and Flag and raised kerbs	The stop is used by local residents during the day.	Requested by Parish	8 months	£6,500	Green

KEY	
Green	A high priority scheme
Amber	A medium priority scheme
SAN THE SECOND	A scheme which is against Essex Policy or there is no
200	appropriate engineering solution.

Capital Highway Improvements Programme

Essex Intelligent Traffic Systems

Braintree

31		originatir g date					
	Ref		Location	Measure	Benefit	Budgetary Cos	
							RAG
1	 IT687	Aug-12	Braintree - Two SCOOT regions in Braintree one along Pierrefitte Way and the other along South Street and Railway Street	recommendations	Journey time improvements	£30,000	Amber
2	IT690	Aug-12	A131 Great Notley north of Bridge End Lane.	Installation of Variable Message Sign northbound. Section 4.4.1 and 5.2	Advise of problems on the M11, A120 & A131.	£95,000	Amber

£125,000.00

Dedicated Right Turn lane at signals	A high priority scheme
Amber	A medium priority scheme
Red	A scheme which is against Essex Policy or there is no appropriate engineering solution.
SCOOT	Split Cycle and Offset Optimisation Technique. This calculates the flow of vehicles along each spur of a junction and can then calculate the timings of the signals required to deal with heavier or lighter amounts of traffic during each cycle of the signals. Particularly good for peak and off-peak periods.

		ginatin ate Location	Scheme	Problem	Scheme sponsor	Estimated Cost (£)	RAG
The state of the s	BRA06	Braintree	Signing installation - Designed and ready to go		Cycling Officer/CTC ride to ride rep	£50,000	Green
-	T715	Witham Conrad Road	Cycleway	5 schools in close proximity and no cycling provision to link into nearby housing areas	From LTP2	£50,000	Amber
	IT720	Coggeshall Road/Rayne Road.	Cycleway	Main traffic corridor into Town Centre with one- way system as barrier	From LTP2	£50,000	Amber
i i	IT730	l Howbridge Road/Dengie Close, Witham		Access to schools from Howbridge Road. Path widening required	From LTP2	£40,000	Amber
	IT732	Forest Road, Witham	Cycleway		From LTP2	£148,000	Amber
-	IT733	Coldnailhurst Avenue, Braintree	Cycleway	, .,	From LTP2	£20,000	Amber
	IT752	A1017, Sible Hedingham	Dedicated Right Turn lane at signals		From LTP2	£20,000	Amiser
	IT770	Freeport to Mill Hill	Cycleway		Cycling Group	£20,000	Amber
	IT772	Town Centre	Town Centre Cycle links		Local Trans Plan 2	£15,000	Amber
1	IT773	Bocking	Cycleway		Local Trans Plan 2	£300,000 £713,000	Amher

A high priority scheme

A medium priority scheme

A scheme which is against Essex
Policy or there is no appropriate
engineering solution.

Amber A medium priority based on Collision History

Ref No.	originat ing date	Problem	Problem	Proposed Solution	Cost (£)	RAG
BRA80	Mar-13	A131 Sudbury Road, Catley Cross, Halstead	there have been three Personal Injury Collisions, one of them serious resulting in one serious and four slight casualties. All three collisions involved vehicles travelling southbound losing control on the left hand bend located 250m south of the junction of Park Road (by Catley Cross Farm).	Install new S bend ahead warning sign with Max Speed 30 sub-plate, on the southbound approach to the left hand bend with accompanying 'SLOW' markings, Install yellow backed chevron sign on the bend, Install reflector posts around the 's' bend, Check and clear the drainage system and Renew all existing white lining for 100m on both approaches to the 's' bend and throughout it.	£7,500	green
BRA81	Mar-13	A131 Mount Hill j/w White Horse Avenue, Halstead	4 Slight Personal Injury Collisions, resulting in five slight casualties. All four collisions involved vehicles turning right from the A131 into White Horse Avenue being shunted by from behind, there is no warning of the junction. The road curves to the left slightly prior to the junction; however any vehicles waiting to turn right can still be seen waiting by approaching traffic.	Install new junction ahead warning sign on the northbound approach to White Horse Avenue with accompanying 'SLOW marking, Install 30mph speed roundel at the 30mph gateway, Clean the 30mph gateway signs and the advanced junction warning sign for Oak Road, Cut back the existing vegetation on the north side of the A13 east of the access into Blamsters Farm to the highway boundary	£2,500	green
BRA82	Mar-13	A131 Notley Green Roundabout, Great Notley	been 8 Personal Injury Collisions (one of them serious) resulting in one serious and 7 slight casualties To continue on the A131 on either approach is not the 'straight ahead' movement motorists may expect given the continuation of the main A131 route	Install lane directional arrows on both approach lanes of both A131 approaches to the roundabout to highlight that left turners should take the left hand lane, Renew the existing circulatory carriageway markings.	£6,000	green
BRA83	Mar-13	Kings Lane j/w A120, Braintree	5 Personal Injury Collisions, 2 of them serious and 3 of them slight resulting in 2 serious and 4 slight casualties. Four collisions involved vehicles exiting Kings Lane failing to give way to traffic travelling eastbound along the A120. The other collision occurred when vehicles on the A120 allowed a vehicle to exit from Kings Lane and an eastbound motorcyclist overtook the vehicles giving way and hit the car joining the A120. The approach to the A120 along Kings Lane is straight however the road curves to the left at the junction which restricts the advanced visibility of the give way sign	Replace the existing give way sign on Kings Lane on a yellow backing board. Relocate the sign if possible so that it is more visible for approaching motorists, Renew the existing white give way lines, central hatching and triangle at the junction, Install new advanced give way sign on Kings Lane with distance sub-plate	£2,750	green

Printed on 20/06/2013 Page 9 of 9

		 			
				×	
					20

Improvement Schemes Against Essex Policy or no appropriate engineering solution

	ID	originatir g date	Location	Scheme	Problem	Justification / Comments	Requested By	Estimated Cost (£)	RAG
1	BRA35	Nov-12	Delvyn's Lane byway from its junction with Church Street, Gestingthorpe	Removal of vehicle right of way	byway unusable by pedestrians and cyclists	When the law was brought in it specifically did not allow byways to become restricted byways. The only way of legally removing vehicular rights (motorised or other) is by a TRO. However the whole byway issue countywide is being looked at. We cannot put in a TRO without a policy in place (we have been legally challenged before by the 4X4 people trying to do this).	GESTINGT HORPE PARISH COUNCIL	n/a	Red
2	IT855		Spa Road, Witham	Pedestrian crossing with central island	Difficult to cross road	Main desire lines have existing crossings. New controlled crossing would not meet ECC requirements, may be unsafe. Uncontrolled crossing should not affect Strategic Route. Do Panel want further investigation?	From Reserve Lis	£40,000	Red
3	IT044	· · · · · · · · · · · · · · · · · · ·	The Causeway, Toppersfield	Footway adj to carriageway, poles to be relocated	Inadequate footway provision.	Unclear where footway is. Poles all seem to be in gardens. Given limited amount of footway spending £35k moving poles appears excessive.	From Reserve Lis	£35,000	Red
4	ГТ028		Maldon Road B1019, o/s Village Hall nr Woodham Drive, Hatfield Peverel	Illuminated zebra crossing poles	Lack of visibility to crossing point.	Previously investigated. Ongoing maintenance issues / costs. Agains Maintenance policy - Recommend no further action.	From Reserve Lis	£12,000	Red
5	I T03 6		New Street, Braintree		Narrow footway. Well used by pedestrians as major route to Town Centre from South.	Current Braintree Urban Realm projects - would this be better as a shared space? Insufficient space for footway; too high flows for shared space; unclear what can be done but suggest that this road is included in main strategy for Town centre.	From Reserve Lis	t N/A	Red
5	I T03 5	···	Millennium Way / B1018 Galley's Island roundabout.	Galley's Island Roundabout Improvements	Congestion	Unclear what can be done to reduce size of garden centre / improve roundabout.	Bus Company	N/A	Red
7	IT018		Bures, Station Hill	Widen Footway/buildout, involves drainage	· · · · · · · · · · · · · · · · · · ·	Scheme unlikely to be cost effective. Against Traffic management policy.	From Reserve Lis	60k	Red

Improvement Schemes Against Essex Policy or no appropriate engineering solution

	ID	originatir g date	¹ Location	Scheme	Problem	Justification / Comments	Requested By	Estimated Cost (E)	RAG
8	IT022		Church Street junction Bovingdon Road, Bocking	Pram Crossing and central island	Difficult to cross road	Investigated, no suitable, safe location.	From Reserve List	£20,000	Red
9	IT032		Junctions between Claud Ince Avenue / Jeffreys Road and Claud Ince Avenue / Mill Road,	Junction Protection Markings	Narrow carriageway, potentially difficult turns for buses	Junction protection markings are against maintenance policy, investigate to identify alternatives. Pass to parking partnership	Bus Company	N/A	Red
10	IT864	in the second	Cressing - various locations	New gateway signs which could carry 'reduce your speed' message, narrowing lines and 20mph roundels, 150mm wide edge of carriageway lines, 'SLOW' markings, where width reduces below 5.5m, remove centre line.	Perceived speeding issues	ECC do not fund gateway signage, the speed limit is 30mph - 20mph roundels are not appropriate. Parish Council to fund if required.	From Reserve Lis	£25,000	Red
11	IT866	Ė:	Witham - various locations	VAS sign faces.	Perceived speeding issue.	Location requires specifying. Ongoing maintenance issue.	From Reserve Lis	£5,000	Red
13	BRA03	2 2	Mayland Road, Witham	dropped kerb	Disabled residents using mobility scooters are unable to move off the pavement fronting	a private road and therefore not Highway Maintainable at Public Expense	Clir Lager	£3,000	Red
	BRA10		WAR MEMORIAL JUNCTION WITH BAKERS LANE AND WITHAM ROAD BLACK NOTLEY	to avoid vehicles coming out at the same time as vehicles turning into / out of the other turning	Concerns raised by a number of residents and the result of a number of accidents	Accident history shows one personal injury accident in 3 years. Narrowness of spur at war memorial regulates traffic speed and limits the vehicles that can undertake this manoeuvre.	Cllr Lager	N/A	red
	BRA63	Nov-12	Acacia Gardens and Mulberry Gardens, Witham	A single post and rail type barrier on the inside of the bend would force cyclists to the outside of the bend increasing the visibility.	Cyclists speed down this alley have collided with people and objects at the bottom, where there is a slight turn impeding full visibility	staggered barriers are against policy as they create issues for mobility users and pushchairs, 1.2m must be left open for accessibility. LHP rejected proposal in March 2013	Clir Lager	£1,000	red

KEY

A scheme which is against Essex
Policy or there is no appropriate
engineering solution.

Improvement Schemes - Agreed

arigir ID	n date Location	S∈heme	Problem	Justification / Comments	Requested By	Estimated Cost (E)	RAG	Recomme orded by LHP	Approved by Cabine member
ITIB65	Newland Street pw The Grove, Witham	Improvements to pedestrian crossing/ tactile paving	Limited accessibility to crossing point	Two collisions at site	From Fisherve Luxt 30	£3,060	Green	Jul-12	Aug-12
Notta.	A1917 Gt Yeldham opposite oek tree	Haiden surface and install footway, Extension of existing footway	No footway (wallrable verge + or verge parting). Vehicles reversing onto carragiway	Aim of scheme is to evoid reversing vehicles. Available area is not wide enough to allow perpendicular parking as well as running lane. Low cost option has space for three care, so is not an ideal solution, however to achieve more spaces would increase costs greatly and could cost up to £200k. To gain any further spaces would mean introducing a retaining well to protect the properties to the west of the site.	From reserve list	£200,000 to solve problem, £35,010 for less cost option Low Cost Option , eclected 10/9/12	Ahlodi	Sep-12	8 : p-12
BPA04↑	MANOR STREET, BRAINTREE	AMEMDED PARKING RESTRIC DONS	ECC's budget for TROs was transferred to the NEPP on its creation and whilst funding has been found for some outstanding schemes, including Meat Farm Witham, it does not have any funding with which to deliver the one at Manor Street	That 'one-off' capital funding of £15,000 be allocated from the Highway Panel's 2012-13 budget to the North Essex Parking Partnership to enable the parking scheme for Manor Street, Braintree to be progressed without further delay		£15 000		Sep-12	Oct-12
iT031	Inworth Road, Feering	Extension of existing footway	No fockway	\$106 Funding due to expire in 2214, land issues. Additional funding required. 2 dight collisions recorded.	From Resouve List 2	Muximum contribution of £120,000 required £22,000 \$109 funding available	General	Nov-12	Dec-12
3RA09	Drury Lane and Church Lane, Fodgewall	SPEED INDICATOR DEVICES (SID)	speeding traffic	No issues. Sensible solution to a valid problem. Existing post for temporary VAS can be used for the southbound traffic, meaning a single post is needed, reducing costs. The BSF has agreed to provide 50% of the balance required but only if the other 50% can be obtained from the Local Highways Panel.	Ridgewell Pansh Council	E6000 (£4.366 required plus cost for post and foundation)	green	Now-12	Dec-12
17037	Newland Street / Maldon Road	Ocngosticn Improvements	Congestion	Junction requires re-modelling. Maybe necessary to remove substandard lenes. Could be possible to wider footways at this location. Investigate. Would require Essex ITS investigation.	Historic - Ongin Unknown	£10,000 investigation Scheme £150,000	Amber	Investigation agreed Nov- 12	Dec-12
T862	B1063 Castle Hedingham to A131 Bulmer tye	7 6 Tonne weight limit TRO revision. Shorter restrictions to aid enforcement.	HGV abuse of restriction	Awaring freight management policy. Problem noted, unclear whe sattractors are so which locations would be most appropriate. An Panel / Perish provide local input? (This is on the strategic route network so any alterations will require formal sign off). Cli Finch aware of signs locations.	From Reserve List	£5,000	Ambe:	floy-12	Dec-12

	gin data				Requested By	Estimated Cost	RAG	Recomme nded by LHP	Approved by Cabine member
ID .	Location	Scheme	Problem	Justification / Comments		121		222	AND REAL PROPERTY.
BRAU2	Ashen Road	7.6 Tonne weight limit	Lorries causing damage to made	egainst poticy will require sign off - Ashen Road is a Local Road in the ECC Functional Poute Hierarchy	Parish Council	£5,000	аг-онг,	140v-12	Dec-12
BRAOS	Rickstones Road, Riventail	verge/bank needs to be cut back a small distance, re-profiled and hard kerbed. The drains may need moving a ahort distance	The verge in Rickstones Road, Rivenhali, near Stoverns Hall Farm, is eroding	In order to obtain a reasonably accurate estimate, stats rearches and a brief survey of the road will need to be undertaken in order to identify prachipaints and the scope of works required, including any stats diversions.	Pansh Council	£3050 treatigation		Nov-12	Dec-12
BRAC7	Coine Poad, Coggeshall near Honywood school	epeed bumps	apreding traffic	Speed humps against policy in 30mph area due to presence of fire station and residences. \$108 funding available for installation of a VAS unit for traffic entering Coggeshall from the A120. This would be a far more appropriate solution, and would address speeding treffic without restricting flow or causing congestion. Even if VAS is installed outside of \$106 process, estimate total cost would not exceed £10k.	Clir (ligel Edey	£10,000	Messer	Nov-12	Dec-12
BRA11	Church Road Twinstead	An advisory sign eracted in the road	Young children are at risk from vehicles travelling in 40mph speed area on Church Road in Twinstead	a children in road sign with Max Speed 20mph aub plate	Clir Finch	12,000	Arthe	Nov-12	Dec-12
BRAZZ	Guithavon Valley/Mill Lane	removing centre line	On road, pavernent, apperland safety		TC/Clir Lagur	000 32	earths)	Nov-12	Dec-12
}P A23	Guithavon Valley/Mill Lane	New roundabout sign for j/w Guthavon Valley/Mill Lano	On road, pavement, speed and safety		TC/Cili Lager	£3,600	u (m)	Nov-12	Dec-12
5RA24	Faulkbourne Road, Witham	Implement a 40mph speed limit on this stretch concerend, Review and ensure appropriate aignage is present.	very poor visibility, safety concerns	According to local residents it is dirigerous and subject of frequent accidents due to speeding. 3 accidents (two sensus) in last three years.	Cl: Lager	£(0.00C	=10=1	Nov-12	Dec-12
BRAIS	Coggoshall Road, Earts Coine between Curds Road and Village Gateway	a reduction in the speed fimit between the two points described	accidents have resulted in personal injuries but also significant damage to properly following impact from errant vehicles. The	Extending the 40 mph zone would affect a few hundred metres, and would reduce the speed of the cars coming down the hill in to Earl's Coine.	Eades Coine Parish Council	£8,000	anibk*	Nov-12	Dec-12
BRA12	South stiFairfeild road	Widening of the junction and removal of traffic aignals	The junction of South Street and Fairfield Road becomes agnificantly congested at peak hours, this is because the namou junction has to be conforted by the first lights.	highway elements will be delivered through Essex		£130,000	green	Nov-12	Dec-12
T820	School Pand , Silver Envi	To widen the road and To re-kerb the northern side of the road, reinstate the verge to a good standard and to plant some appropriate street trace and/or install other measures to protect the new verge.	School Road has been ifor	Widening road in likely to be expensive - will require widening on both sides to main cambor Lovel differences mean that hardening verge not appropriate without additional works. Widening is possible but may set a precedent for future requests. Investigating Long parking buys and widening road.	Panth Council	£150,000 for widening Stats diversions potentially £300,000	amber	Invustigation agrand Nov- 12	Dec-12

Improvement Schemes - Agreed

	origin date					Estimated Cost		scomme and by	Approved by Cables
IT367	Cal: Road, Riventall	Scheme "route unsuitable for HGVs" weight restriction	2 large vehicles cannot safely pass each other in Oak Road due to the narrow road width. This causes HGVs to run along the pavements.	Pansh Council have offcred to pay for scheme, scheme was agreed for the £6,000 to be paid by PC. Scheme needs further data to ascertain the potential affects of this scheme.	From Reserve	500) (from PC)	RAG	01/09/2012	membe
BRA27	Batt Hall (Bulmer Road, Sulmer, Essex)	Vehicles are restricted to one side of the road and is only subjected to the national speed limit for rural roads currently 60mph, which is often exceeded	40 MPH Buffer, repeater signs including posts and foundations installed in verge, some minor hedge trimming to suit visibility. TRO including publicity	Location appears enpropriete for a 40mph buffer zone, as identified in the Speed Management Policy. The stretch of road past Batt Hall does not qualify as a "Village", and the houses are not significant traffic generators, thereby negating a need for 30mph restriction. The road would be more suitable for a 40mph restriction as the downhill alignment coming towards Sudbury would make reducing to 30mph difficult, and could lead to a higher risk of accident	Parish Council	£10 000	Green	Jan-13	Jan-13
RA26	Messingham Divvo, Earls Coine at its Junction with A1124 Haistead Road		upgrade of current singage	Issue will be HGV's approaching Earls Coine from the north-west, from Halstead. There is currently an existing "Unsuitable for HGV's" sign on the entry to Massingham Drive. It is suggested that this sign is replaced with a pictoral version, with the text replaced by an arrow as appropriate. Due to the size of the sign plate, it is envisaged that the plate will have to go on it's own new posts. Post will need careful location so as to avoid any underground services.	Panah Council	£2,000	gteen	Jan-13	Jan-13
₹A29	Come Road Coggesha!	The lack of a footpath between the Fire Station and Wisdoms Green Coine Road Coggeshall endangers children walking to and from school due to the speed of the traffic using this road	The fitting of speed bumps on the road which only allow traffic to straddle them thus slowing the traffic down	Speed humps are against ECC policy (Road is a secondary distributor PR2), as well as an additional maintainance expense. Speed humps would also create significant extra noise, both impact noise of vehicles hitting the speed bumps, and the additional engine noise accelerating away in addition, there is a fire station nearby for which access cannot be restricted suggests installation of a 30mph VAS sign targeting southbound traffic coming from the A120	Parish Counci	£6000 (VAS)	a iba	Jan-13	Jan-13
₹A30	B1018 Cressing	This section of road was the subject of a short report in 2010. The report outlined the risks of sideswipe accidents, nose-to-tails, accidents involving pedestrians, and accidents caused by the seventy of the bend	To widen the existing alignment, the works would cost in the region of £205k + land purchase costs (at 2010 prices). To remove the dogleg bend altogether would cost approximately £1.125M + land costs	The report suggests the localised widening as a preferred option, this is a sensible option and would be the suggestion to the LHP	Clir Etley	230 000 Plub land	anae	10,000 investigation approved jan 13	
859	06k Road Railway Bridge, Rivenhall	Signal controlled one-view system and pedastrian guard rail, footpath widening	Narrow roadi narrow prith unrier railway bridgo	Signal scheme would not be appropriate, given high costs and lack of collision history. A sign controlled prolify we king may be more appropriate. On atrategic network so egainst policy. Panel agroed to draw up scheme. Full cost has not been identified, however LHP wish to allocate further 35k ontop of the 10k however not to be committed until drawings are completed.	From Reserve List	£45,000	ainber	Jen-13	Jan- 13
A6	B1024 Earls Coine to	Additional "SLOV" markings and refurbished edge markings will help to reduce vahicle speeds on approach to hazardous sections of road		5no. PIA's in 3 yr history, however, only one was a head- on collision between two cars. The other accidents are loss of control accidents but for varying reasons.	Coggesha Il and Earls Colne Parish Councils	£5,000	greën	Mar-13	Age 15

Improvement Schemes - Agreed

10	origin date Location	Scheme	Protilem	Justification / Comments	Requested By	Estimated Cost (E)	RAG	Recomme rided by LMP	Approved by Cabinet member
BRA4	Church yard/field entrance Dec-12 Church End, Panfield	install 1 deer warning sign with "For 500 yds" distance plate on westbound verge and install 1 deer warning sign) with "For 500 yds" distance plate on eastbound verge at St Marys Close	Several near-misses and two direct hits from deer crossing	No PIA accidents recorded, however evidence on site of deer crossing	Panfield Parish Council	£3,000	green	Mar-13	Apr-13
BRA4	Dec-12 SCHOOL ROAD, Rayne	warning signs	residents are concerned for childrens' safety. Request for warning signs	Erect children warning sign with "For ½ mile" Distance Plate Erect sign in vicinity of junction of School Rd/Milch Ln, on eastbound verge. Erect sign in vicinity of junction of School Rd/Long Ln, on westbound verge	Rayne Parish Council	000,63	grean	Mics-13	Apr.40
BRA3	GREAT MAPLESTEAD Nov-12 various	installing full-height kerbs (125mm face) which will hold the island shape and discourage over-running. Include a more substantial foundation than standard, in order that the kerbs are not damaged by large/long loads.	Erosion of grass surface and dangerous parking	Village 'triangles' are having the edges over-run, which is eroding the isnaid (in terms of size) and dragging mud on to the road. Installation of drop kerbs will not address this	GREAT MAPLES TEAD PARISH COUNCIL	£5,000	green	Mar-13	Арт-13
BRA7	Hatfield Peveral - rotated Jan-13 around sites	Speed Indicator Device	continuing efforts to combat speeding in the villags, the PC seek to fund a further SID	15 locations available but with only three SIDs and an .8/10 week rotation it is difficult to provide effective cover throughout the year	Hatfield Peverel PC	£6,000	amber	Mar-13	.Ар:-13
BRA6	Oct-12 Newland Street, Witham	Request to install a dropped kerbs adjacent to Mayland House	difficult for less mobile residents on mobility scooters	Proposed three dropped crossings, two outside Mayland House and the third to facilitate crossing to the Doctor's surgery	Witham Town Council	£8,000	ambo	Only one approved - adjacent to viayland House March 13	Api-13
IT011 b	A1017 High Street, Gt Former Yeidham (Just North J/w LHP Toppesfield Road)	Extension of existing footway	No foctway (narrow walkable verge)	Demand should be considered. There's an alternative footway on opposite side of carriageway, no collisions - would a crossing point be more appropriate? Will require retaining wall and possible land purchase - The Parish Council now favour the crossing point.	Reserve	£20,000 for crossing point, £150,000 for footpath.	Ambe	Crossing Poil - Mar-13	it Apr-13

<u>KEY</u>

Green	A high priority scheme
Amber	A medium priority scheme
Marie Ale	A scheme which is against Essex Policy or there is no appropriate engineering solution.

Small Works - Approved

ID	origin date	Location	Scheme	Other issues / comments	Requested By	Estimated Cost	RAG	Recomme nded by LHP	Approved by Cabinet member
IT870		Middleton Road/Allen's Hill. Middleton	Signs to show Pedestrians in the road	Supported by police. No collision history.	Reserve list	£2,000	Ambe	Sep-12	Sep-12
BRA13		Gt Maplestead	Speed survey		Gt Maplestead Parish Council/Clir Finch	£300	Amber	Nov-12	
BRA14		Henny Back Road, Lamarsh at junction with Moat Lane	Unsuitable for HGV's		Parish Council	£1,000	Arriber	Nov-12	Dec-12
BRA15		Mill Lane Shryves Corner Colne Engaine	Bend Ahead sign	DUVE STORY - DES	supported by PC	£1,000	Amber	Nov-12	Dec-12
BRA16		Parknali Road/Church Road, Gosfield	Horse and rider signs		Parish Council	£1.000	Amber	Nov-12	Dec-12
BRA17		Church End, Panfield - near Churchyard and by field gate opposite the church	Wild Animals Warning Triangle		Parish Council	£1,000	edita	Nov-12	Dec-12
BRA18		Stamburge	Give Way Warning Triangle		member of public - investigated and feasible	£1,000	amber	Nov-12	Dec-12
BRA19		Audley end of Gestingthorpe, between Crouch House and Moat Farm	Speed survey before SID considered		Gestingthorpe Parish Council	£3:00	airibar	Nov-12	
BRA20		v/gage of Liston	Speed survey before speed change considered		Foxearth and Liston Parish Council	£300	amber	Nov-12	
BRA21		Braintree	Snow Clearance equipment	annual maintenance being met by Braintree DC	Braintree DC	£3,120	arriber	Nov-12	Dep-12
BRA33	The Part of the Pa	Oak Road, Rivenhall (in relation to IT867)	7 day speed, volume and classification surveys (7)	we need to understand the volume of vehicles that would be affected and the impact of rerouting vehicles for the Oak Road Schemes. With this information we can look at the proposal and provide Cllr Louis with the details so that a final decision can be made.	ECC to provide evidence for the scheme	£1,330	green	Jan-13	Jan-13
BRA50		Village of pebmarsh	speed survey	to more accurately evaluate the speeding problem in the village, as a pre-cursor to discussions regarding traffic calming measures (being validated)	Parish Council	£200	amber	Jan-13	Jan-13
BRA78	Feb-13	Sible Hedingham	Snow Plough		Sible Hedingham Parish Council	£2,715	Amber	Mar-13	Apr-13

Small Works - Approved

KEY

Green	A high priority scheme
Amber	A medium priority scheme
Red	A scheme which is against Essex Policy or there is no appropriate engineering solution.

Bus Stop Improvements - Approved

rigin date	Location	Details of Scheme	Issues / Comments / Reason for Scheme	Scheme Origination	Estimate d Cost	Priority (RAG)	Agreed by Panel	Approved by Cabinet member
	2 new bus stop either side of Coggeshall Road Cherry Garden Centre	New stop cutside the Garden Centre and another opposite.	Customers visiting the Garden Centre have request stop outside. The near one otherwise is quite a walk away near the Dolphin PH and is on a hill	Garden Centre Manager on behalf of their customers	£3,000	Green	Jul-12	Aug-12
	Bus Stop: 150024012042, Iron Pear Tree Farm. Address: Braintree Road.	Move bus stop opposite it's partner Install raised and dropped kerb	A Wheelchair user is finding it difficult to use the bus due to the position of the stop and would benefit from raised kerbs being installed.	Requested by a member of public who is a carer for a wheelchair user	£3,000	Green	Jui-12	Aug-12
	Bus Stop 150024013019, Hospital. Address Hedingham Road, Haistead	Move ous stop to outside Hospital and install a wooden shelter	At present the bus stop is on a narrow path, the idea is to move the location of the stop near to the entrance of the Hospital where the path is wider and install a shelter for patients, staff and visitors	Requested by local residents & Parish Council	£10,000	Green	Jui-12	Aug-12
	Bus Stop ID 1500AA146 The Swan Inn Hatfield Peverel	Essex Police have requested the bus stop is moved away from the Zebra Crossing on The Street Hatfield Peverel near Swan Close. The existing shelter is too large to fi in a new location identified so the Parish Council have asked for it to be moved to Maldon Road Hatfield Peverel. ECC plan to reuse a smaller reconditioned shelter at the new location.	An incident occurred when a bus passenger alighted from a bus on the B1137 The Street. Hatfield Peverel at the bus stop near junction of Swan Close and crossed on the zebra crossing behind the bus and was struck.	Requested by Essex Police or safety grounds and supported by the Parish Council	£5,000	Green	Sep-12	Sep-12
	Bus Stop: 15005014, Clare Road, Address London Road, Braintree	Design and implementation of a bus build out	At present the buses cannot access the stop due to parked cars and they are stopping in the middle of the road which dangerous and difficult to board and alight from. The build out will only displace up to 2 parking places where as a bus cage would remove 6.	Requested by local bus operator	£10,000	Green	Sep-12	Sep-12
	Bus Stop: 1500IM1168, The Memorial Address: Rowley Hill, Sturmer.	install new bus stop with wooden shelter and hardstand	School children wait at this location and the Parish have requested a new stop with a shelter	Requested by Parish Council	£10,000	Green	Sep-12	Sep-12
	Bus Stop 15003900801, Honeysuckie Way Shop Address Honeysuckie Way	Install new wooden shelter	Would benefit local Greenfield Housing Ass Residents and is being championed by Clir Rose	Requested by Clir Rose on behalf of the local residents	£7,500	Green	Sep-12	Sep-12

Bus Stop Improvements - Approved

in date	Location	Details of Scheme	Issues / Comments / Reason for Scheme	Scheme Origination	Estimate d Cost	Priority (RAG)	Agreed by Panel	Approved by Cabinet member
	Bus Stop: 150003900804, Pennyroyal Crescent, Address: Bramble Road, Witham.	Install new wooden shelter	Would benefit local Greenfield Housing Ass. Residents and is being championed by Clir Rose	Requested by Clir Rose on behalf of the local residents	£7,500	Green	Sep-12	Sep-13
	Bus stop ID 1500AA146 The Swan Inn Hatfield Peverel	Relocation of old shelter from the The Street Hatfield Pevarel	The new location for the shelter is too small for the existing shelter so a new shelter will need to be installed and the old one relocated. The plan is to reuse a metal shelter we are removing from Brentwood due to constant vandalism, relocate Hatfield Peverel's large wooden shelter to a site in Margaretting that needs a larger shelter. In turn Margaretting PC will give their smaller wooden shelter to Hatfield Peverel PC to install on Maldon Road Hatfield Peverel.	Parish Council request	£3,000	Ambur	Sep-12	Sep-1
	Bus Stop 1500 -2 new bus stops on Church Road Rivenhall near West Ford Farm CM8 3PG BRA05	Install a stop either side of the road work consisting of hardstands poles and flags	Resident at West Ford Farm has mobility	Resident with mobility difficulties supported by PC.	£5,000	Green	Sep-12	Oct-1
	Upper Holt Street, stop ID 2009COLN Coine Priory	Install Shelter in pavement -not wood. Scheme combined with 15002009COLN	For bus passengers comfort - P/C to write to local residents	Raquested by Parish Council	£4,000	Green	Nov-12	Dec-1
	New stop on Witham Road near the junction of Meadow Way BRA26	Install wooden Shelter on grass verge	stop is used by local residents and school children daily	Requested by member of public but has been endoised by the Parish Council	£10,000	Green	Nov-12	Dec-1
	Bus Stop: 15003900801, Honeysuckle Way Shop: Address: Honeysuckle Way.	Installation of raised kerbs	Would benefit local Greenfield Housing Ass Residents and is being championed by Clir Rose	Requested by Clir Rose on behalf of the local residents	£3,500	Green	Nov-12	Dec-1
	Bus Stop: 150003900804, Pennyroyal Crescent Address: Bramble Road, Witham	Installation of raised kerbs	Would benefit local Greenfield Housing Ass. Residents and is being championed by Clir Ross	Requested by Clir Rose on behalf of the local residents	£ £3.500	Green	Nov-12	Dec-1
	Bus Stop ID 15002009COLN Upper Holt Street Earls Coine	Install cantilever shelter with seat - not wood requested - combined with 2009COLN	Request from the Parish Council - they were promised this shelter last year but funds did not allow.	Parish Council request	£4,000) Amber	Nov-12	Dec-1
	The Kennels, Halstead Road stop (D 27007008	install Shelter in pavement		Requested by Pansh Council	£7,50	Green		Dec-1
	BRA51 -Mount Hill, white Horse Avenue Halstead	Install 2 bay haif end panels metal shelter. There is already a base at this location. Installation of raised kerbs to aid passengers board and alight	Heavily used stop - Parish Council have written to local residents	Requested by Parish Council	£7,50) Green	Jan-13	Jan-1

Bus Stop Improvements - Approved

gin date	Location	Details of Scheme	Issues / Comments / Reason for Scheme	Scheme Origination	Estimate d Cost	Priority (RAG)	Agreed by Panel	Approved by Cabinet member
	BRA52-church End Deanery Hill Panfield	Install new wooden shelter at axisting bus stop	The old shelter which belonged to the Parish Council has been demolished and the Parish are asking ECC to fund its replacement	Requested by Parish Council	£7,500	Green	Jan-13	Jan-13
	BRA53-Outside Paycock House West Street Coggeshall	Install new wooden shelter at existing bus stop	Request for a shelter from a member of the public who points out West Street has no bus shelters but does have many visitors to the 2 National Trust properties in the area.	Requested by a member of public, supported by Coggeshall PC	£ 7,500	Green	Jan-13	Jan-13
	BRA55-Elizabeth Avenue, Laurence Avenue, Witham	înstalî a new wooden shelter	Stop is in a busy residential area near local shops	Requested by Braintree DC. Cilr Elil Rose from Witham Town Council and Greenfields Housing Ass Support the schemes too	£7,500	amber	Jan-13	Jan-13
	BRA56- Flora Road 1500(M821	install wooden shelter	The existing shelter is old and shabby, installing a new wooden shelter would benefit bus users and be in keeping with other new shelters in the area.	Requested by Braintree DC, Clir Bill Rose from Witham Town Council and Greenfields Housing Ass Support the schemes too	£7,500	amber	Jan-13	Jan-1
	BRA57-Bramble Road, flora Road 15003900901	Remove cld metal shelter and replace with a new shelter	The existing shelter is old and shabby, installing a new wooden shelter would benefit bus users and be in keeping with other new shelters in the area	Requested by Braintree DC, Clir Bill Rose from V-tham Town Council and Greenfields Housing Ass Support the schemes too	£7,500	amber	Jan-13	Jar-1

L P T	

Green	A high priority scheme
Amber	A medium priority scheme
Red	A scheme which is against Essex Policy or there is no appropriate engineering solution.

School Crossing Patrol - Approved

Site No	origin date Schoo	Location of patrol	Work required	Problem	Origin of request	Total Estimated RAG Coats	Recommended by LHP	Approved by Cabinet member
60134	Templars Primary Sch	Cressing Rd, Witham	Pedestrian guardrail, dropped kerbs and tactile paving	Poor accessibility for pram/mobility restricted users. slip/trip hazard	ECC Site safety assessment	£2,950 Green	Jul-12	
60141	St Michael's Primary School/St Fri Catholic Prii School	ancis	Dropped kerbs/tactile paving	Poor accessibility for pram/mobility restricted users	ECC Site safety assessment	£2,950 Græn	Jul-12	Aug-12
Kr.	Holy Family Primary Sch		complete removal of signs/post 545/547 1	Site has been redundant for several years incorrect sign gives drivers misleading information	ECC Site safety assessment	£2,000 Green	Jul-12	Aug-12
60118	John Bunya Infant & Jun Schools		Dropped kerbs and tactile paving	Poor accessibility for pram/mobility restricted users	ECC Site safety assessment	£2,950 Ambur	Jul-12	Aug-12

<u>KEY</u>

Green	A high priority scheme
Amber	A medium priority scheme
200 1	A scheme which is against Essex Policy or there is
Hed	no appropriate engineering solution.

Cycling Schemes - Approved

ID	origin date Location	Scheme	Problem	Scheme sponsor	Estimated Cost (£)	Timescale	RAG	Recomme nded by LHP	Approved by Cabinet member
17769	Blackwater Lane to Pasture Road Blackwater Rail Trail, Witham	f. Cycleway	Sub-standard cyclepath condition	apc	28.000	3 months	Green	Jul-12	
T753	John Ray Park	Cycleway		through PROW, Cycling	overall £302,600, due to Growth Area Funding £100,000 required	Designed - Ready to go	Green	Jan-13 providing local ly supported scheme	ار الاستان الاستان
17754	Vernon Way to Blackwater Way	Cycleway		ECC/BDC	£30,000	Designed - Ready to go	Green	Jan-13 providing local ty supported scheme	Jan-13

KEY	
Green	A high priority scheme
Amber	A medium priority scheme
Red	A scheme which is against Essex Policy or there is no appropriate engineering solution.

PROW - approved

PROW Number	Parish	Status	Scheme	Problem	From	Timescale	Cost (E)	Notes	RAG	Recomme nded by LHP	Approved by Cabinet member
19	Great Bardfield	Byway	Surface and drainage improvements	Heavily rutted and waterlogged. Only passable to skilled off road motorised users	County Councillor	2 months	£15,000	Improvements to the sub base, wearing course and improvements to the drainage system to enable the pyway to tolerate passage by the various types of users and the increase in volume of traffic.	100	Jul-12:	Aug-12
27, 28	Haistead, Boisfield Terrace and Baptist Church to Mill Lane	Footpath	Surface and drainage improvements	Blacktop badly breaking up casuing major tripping hazard	County Councillor	4 month	£17,000	Large scale surface improvements to a very busy footpath	Green	Sep-12	Sep-12

KEY	
Green	A high priority scheme
Amber	A medium priority scheme
Kes	A scheme which is against Essex Policy or there is no appropriate engineering solution.

Casualty Reduction - approved

Ref No.	Location	Problem	Proposed Solution	Cost (£)	RAG	Recommende d by LMP	Approved by Cabinet member
52	B1018 Witham Road Jw Temple Lane	Right-turn collisions	Clear vegetation across inside of bend	£3,500	Green	Jul-12	Aug-12
52		The state of the s	Clear vegetation across inside of bend	£3,500	Graen	Jul-12	Aug-12
KEY	A high priority based on Collision	history					
Amber	A medium priority based on Collis	ion History					
led	A scheme which is against Essex	Policy or ther	e is no appropriate engineering solution.				
	Scheme pending Validation		-				

		· ·
		•
		*

Reference Mumber	Tesh Manne	Works Description	Finish	Cost Code	Allocated
DC1231	B1018 Witham Road j/w Temple Lane, White Notely	y Casualty reduction measures	Thu 21/02/13	LBRA001001	£3,499.00
	Design		Fri 04/01/13		
			Thu 20/02/13		
DC1283	Holy Family RC Primary School, Hatfield Road / Allectus Way, Witham	Signage works (inc. design)	Fri 05/04/13	LBRA006003	£2,000.00
	Design		Fri 21/12/12		
	Construction RSA 4 / Defect Period Review		Fri 05/04/13		
DC1284	John Bunyan Infant & Junior School, Coldnailhurst	Part of the second	TII 04/04/14		
	Lane, Braintree		Fri 12/04/13	LBRA006004	£2,950.00
	Construction		Fri 04/01/13		
	RSA 4 / Defect Period Review		Fri 11/04/14		
DC1285	St Michael's C of E Primary School / St Francis	Tactile crossing	Fri 12/04/13	LBRA006002	£2.950.00
	Design		Eri 21/12/12		
A section of the sect	Construction		Fri 12/04/13		
	RSA 4 / Defect Period Review		Fri 11/04/14		
DC1286	Templars Primary School, Cressing Road, Witham	Tactile crossing	Fri 12/04/13	LBRA006001	£2,950.00
	Design		Fri 21/12/12		
	Construction RSA 4 / Defect Period Review		Fri 12/04/13		
DC1406	File County		+1/-0/-1		
	Atot night street, Great Telanam (opp Oak Iree)	Layby works	Fri 11/10/13	LBRA002002	£35,000.00
	Design		Fri 14/06/13		
	RSA 4 / Defect Period Review		Fri 10/10/13		
DC1408B	Clare Road / London Hill, Braintree	Bus stop improvements	Fri 10/10/14	LBRA005004	£10,000.00
	Design		Fri 21/06/13		
•	RSA 4 / Defect Period Review		Wed 23/04/14		
DC1473	Colne Road, Coggeshall	VAS sign installation	Fri 11/10/13	LBRA002022	£6,000.00
	Construction		Wed 31/07/13		
	RSA 4 / Defect Period Review		Fri 10/10/14		
DC1484	B1053 Braintree Road j/w Church End, Shalford	VAS sign installation	Wed 13/11/13	LBRA002018	£6,043.00
	Design		Wed 31/07/13		
	RSA 4 / Defect Period Review		Wed 13/11/13		
DC1494	Church Road, Rivenhall	Bus stop improvements	Wed 12/06/13	LBRA005005	£5,000.00
	Design		1/04/		
	Construction RSA 4 / Defect Period Review		Wed 11/06/13		
DC1328	A1124 Hedingham Road, Halstead (Hospital Bus	Bus stop improvements	Fri 20/09/13	LBRA005002	£10.000.00
	Stop)				
	Construction		Fri 20/09/13		
	RSA 4 / Defect Period Review		Fri 19/09/14		
DC1329	Newland Street j/w The Grove, Witham	Tactile crossing	Mon 17/06/13	LBRA002001	£3,000.00
	Design				
	RSA 4 / Defect Period Review		Tue 18/06/13		
DC1338	Braintree Road (Iron Pear Tree Farm)	Bus stop improvements	Tue 20/08/13	LBRA005001	£3,000.00
	Design		Fri 28/06/13		
	Construction		Tue 20/08/13		
DC1407	MSA 4 / Defect Period Keview Middleton Road / Allen's Hill, Middleton	Signage works (inc. design)	Tue 30/07/13	LBRA002003	£2,000.00
	Design		Fri 07/06/13		
	Construction		Tue 30/07/13		
DC1408D	NSA 4 / Defect Period Review		Tue 29/07/14		
DC1408D	Design	Bus stop improvements	Thu 25/04/13	LBRA005004	£7,499.00
	Construction		Tue 30/04/13		

Distinguish Content Ennish Road, Withins Bus stop improvements The 30,00433 Libradozono Engineery Controversion The 30,00433 Libradozono Engineery Controversion The 30,00433 Libradozono Engineery Controversion Controversion	Reference Number	Task Name	Works Description	Finish	Cost Code	Sugget
Constitution Cons	1408E	Pennyroyal Crescent, Bramble Road, Witham	Bus stop improvements	Tue 30/04/13	LBRA005004	£7,499.00
Start Points Evend Review International Points Internation		Design		Thu 25/04/13		
Stand Street Free District Free District		Construction		Tue 30/04/13		
Design	E.A.1	KSA 4 / Defect Period Review		Wed 01/05/14		
Controlled	141	South Street and Fairfield Street, Braintree	Junction improvement	Fri 28/02/14	LBRA002004	£130,000.00
15.200.21.44 Control Con		Vesign		Fri 09/08/13		
10.00		Construction		Fri 28/02/14		
Controlled				Fri 27/02/15		
Design Construction Constructi	545		Speed limit	Tue 30/04/13	LBRA002005	£6.000.00
Controlled		Decign		TL.: 25 /04 /43		
Risk At J Defect Priord Sevene Speed limit The 85/06/31 at LBRA002008 EL Construction The 25/04/31 at LBRA002007 E Construction The 25/04/31 at LBRA002007 E Stat A / Defect Priord Sevene Sprage works (Inc. design) No. 14/10/31 at LBRA002007 E Construction The Sprage work (Inc. design) No. 14/10/31 at LBRA002009 E Construction The Sprage work (Inc. design) No. 14/10/31 at LBRA002009 E Construction The Sprage work (Inc. design) No. 14/10/31 at LBRA002009 E Construction The Sprage work (Inc. design) No. 14/10/31 at LBRA002009 E Construction The Sprage work (Inc. design) No. 14/10/31 at LBRA002009 E Construction The Sprage work (Inc. design) No. 14/10/31 at LBRA002011 E Construction The Sprage work (Inc. design) No. 14/10/31 at LBRA002012 E Construction The Sprage work (Inc. design) The 12/10/31 at LBRA002011 E Design The Sprage work (Inc. design) The 12/10/31 at LBRA002011 E Design The 12/10/31 at LBRA002011		Construction		Tue 30/04/13		
Design		RSA 4 / Defect Period Review		Wed 01/05/14		
Design	543	Faukbourne Road, Witham	Speed limit	Tue 30/04/13	IBRADO2006	610 000 00
RSA 4 Defect Period Review Wed 51108/14 ERA002007 E	,	Design		Thu 25/04/13	2007000	2700000
Start Design		Construction		Tile 30/04/13		
Contribution valley Mill Line Signage works (fine, design) Min		RSA 4 / Defect Period Review		Med 01 /05/1/		
Construction Cons	544	Guithavon Valley / Mill Jane	out ofwor	Wed 01/05/14	1000000	
Confrontion		Design	WOLKS THE	Mon 14/ 10/ 13	LBKAUUZUU/	£3,000.00
Construction		Construction		FII 20/01/13		
Construction Main 14/10/13 in Linkou2008 Edition valiety / fullit Line Inhing works Mino 14/10/13 in Linkou2008 Edition Design Construction Fin 20/07/13 in Linkou2009 Edition Fin 20/07/13 in Linkou2009 Edition Construction RAA 1 Defect Period Review Signage works (finc. design) Fin 21/06/13 in Linkou2009 Edition Design Church Road Twinstead Signage works (finc. design) Fin 21/06/13 in Linkou2009 Edition Church Road Twinstead Signage works (finc. design) Fin 21/06/13 in Linkou2001 Edition Design Church Road Twinstead Mon 11/06/14 in Linkou2001 Edition RSA 4 Defect Period Review Traffic calming Fin 23/06/13 in Linkou2001 Edition RSA 4 Defect Period Review Traffic calming Fin 23/06/13 in Linkou2001 Edition Posign Design Fin 23/06/13 in Linkou2001 Edition Posign Fin 23/06/13 in Linkou2001 Edition Fin 23/06/13 in Linkou2001 Edition Posign Fin 23/06/13 in Linkou2002 Edition Fin 23/06/13 in Linkou2002 Edition Posign Fin 23/06/13 in Linkou2002 Edition Fin 23/06/13 in Linkou2002 Edition Fin 24 Defect Period Review Fin 23/06/13 in Linkou2002 Edition Fin 23/06/13 in Linkou200		RSA 4 / Defert Period Review		Mon 14/10/13		
Design	545	Guithavon Valley / Mill Jane	of som being	Mon 13/10/14	00000000	00000
Construction Productive Production P		Decion		F.: 20/20/13	LBKAUUZUU8	£5,000.00
Stack of Period Review Note of the Control of t		Construction		Fri 26/01/13		
Signage works (inc. design) Fri 12/07/13 1874,002009 E.		RSA 4 / Defect Period Review		Mon 12/10/13		
Design	546	School Lane, Silver End - FEASIBILITY ONLY	Board widening	MOII 15/10/14	DOOCOON	0000000
Councing Councing		Design	0	Fri 21/06/13	LBINACOZOGO	E.10,000.01
Design	.547	Church Road Twinstead	works (inc.	Mon 12/08/13	LBRA002010	£2.000.00
RSA 4 Defect Period Review Mon 12/08/13 LBRA002011 EL Construction Co		Design		Fri 24/05/13		
RSA 4 Defect Period Review VAS sign Installation Thu 35/04/13 IBRA002011 £1		Construction		Mon 12/08/13		
Cohe Road, Coggeshall VAS sign installation The 30/04/13 LBRA002011 £1 NASA 4 / Defect Period Review Traffic calming Fri 15/09/13 LBRA002012 £ Newland Street Verificationes Road, Rivenhall - Feasibility only Fri 15/09/13 LBRA002012 £ Pesign Construction Fri 15/09/13 LBRA002013 £1 Construction Construction		RSA 4 / Defect Period Review		Mon 11/08/14		
Packing Packing Packing Packing	548	Colne Road, Coggeshall	sign	Tue 30/04/13	LBRA002011	£10,000.00
Rick At Defect Period Review Parking calming Parking Cology Parking Control Road, Witham Passibility only Passibility Passibi		Design		Thu 25/04/13		
Newland Street Venthal Feasibility only Traffic calming Fri 26/07/13 LBRA002012 & Easibility only Design		RSA 4 / Defect Period Review		Wed 01/05/14		
Pesign	549	Rickstones Road, Rivenhall - Feasibility only	Traffic calming	Fri 16/08/13	LBRA002012	£3,000.00
Fig. 2006/13 Encoupling only		Design		Fri 26/07/13		
Pesignality any	1550	Newland Street J/w Maldon Road, Witham -	Junction improvement	Tue 12/11/13	LBRA002013	£10,000.00
Construction Tue 11/11/14 Tue 11/11/14 Tue 11/11/14 Find 4 / Defect Period Review SID sign installation Tue 11/11/14 Tue 11/11/14 Design Construction Mon 29/07/13 LBRA002014 £ End 29/07/14 RSA 4 / Defect Period Review Find 12/07/13 Find 12/07/13 End 29/07/14 RSA 4 / Defect Period Review Footway (new) Find 12/07/13 End 20/07/13 RSA 4 / Defect Period Review Footway (new) Find 12/07/13 End 20/07/13 RSA 4 / Defect Period Review Find 12/07/13 End 20/07/13 End 20/07/13 RSA 4 / Defect Period Review Find 12/07/13 End 20/07/13 End 20/07/13 RSA 4 / Defect Period Review Find 12/07/13 End 20/07/13 End 20/07/13 RSA 4 / Defect Period Review Find 12/07/13 End 20/07/13 End 20/07/13 End 20/07/13 RSA 4 / Defect Period Review Find 12/07/13 End 20/07/13 End 20/		reasibility only		07/00/00 143		
The 11/11/14		Construction		Tue 12/11/13		
Design		DCA / Potent Barian		Tue 11/11/13		
Design	ï	KSA 4 / Derect Period Review		10e 11/11/14	***************************************	000000
Construction RSA 4 / Defect Period Review Fortway (new) Fri 13/12/13 LBRA003001 £12	100	Decigo	SID sign installation	Fri 10/05/13	LBKAUUZU14	£6,000.00
RSA 4 Defect Period Review Footway (new) Fri 13/12/13 LBRA003001 £12		Construction		Mon 29/07/13		
Inworth Road, Feering Footway (new) Fri 33/12/13 LBRA003001 £12		RCA 4 / Defect Deriod Review		Mon 28/07/14		
Design Construction Fri 12/12/13 Fri 12/12/14 Henney Back Road J/w Moat Lane, Lamarsh Signage works (inc. design) Fri 12/12/14 ERA002015 Fri 12/12/14 ERA002015 Fri 12/12/14 ERA002015 Eri 12/12/14 Eri 12/12/14 Eri 12/12/14 Eri 12/12/14 Eri 12/12/13 Eri 12/12	55.5	Inworth Road Feering	Footway (new)	Fri 13/12/13	LBRA003001	£120.000.00
RSA 4 Defect Period Review Fri 13/12/13 ERA002015 Fri 12/12/14 Fri 12/12/14 Fri 12/12/14 Fri 12/12/14 Fri 12/12/14 Fri 12/12/13 ERA002015 Fri 12/12/13 ERA002015 Fri 12/12/13 ERA002016 Fri 12/12/13 ERA002017 Fri 12/12/13 ERA002018 Fri 12/12/13 ERA002019 ERA002019 Fri 12/12/13 ERA002019 ERA	700	Design	(appl) (page)	Fri 07/06/13		
RSA 4 / Defect Period Review Fri 12/12/14 BRA002015 # Henney Back Road J/w Moat Lane, Lamarsh Signage works (inc. design) Fri 12/07/13 LBRA002015 # Design Construction RSA 4 / Defect Period Review Fri 12/07/13 LBRA002016 # Fri 12/07/13 LBRA002016 # Fri 12/07/13 LBRA002016 # Fri 12/07/13 LBRA002016 # Fri 12/07/13 LBRA002017 # Design Construction RSA 4 / Defect Period Review Signage works (inc. design) Mon 15/07/13 LBRA002017 # Design Construction RSA 4 / Defect Period Review Signage works (inc. design) Wed 22/05/13 LBRA002018 # Church End (near church), Panifield Design Construction RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/13 LBRA002018 # Church End (near churchyard and by field gate Signage works (inc. design) Wed 17/07/13 LBRA002018 # RSA 4 / Defect Period Review Thu 15/05/14 LBRA002019 # RSA 4 / Defect Period Review Signage works (inc. design) Thu 18/07/13 LBRA002019 # RSA 4 / Defect Period Review Signage works (inc. design) Thu 18/07/13 LBRA002019 # Thu 18/07/13 LBRA002019 # Thu 18/07/13 Thu 18/07/13		Construction		Fri 13/12/13		
Henney Back Road j/w Moat Lane, Lamarsh Signage works (inc. design) Fri 12/07/13 LBRA002015 & Design Construction RSA 4 / Defect Period Review Fri 11/07/14 Mill Lane Shryves Corner, Colne Engaine Signage works (inc. design) Mon 15/07/13 LBRA002016 Mon 15/07/13 LBRA002017 Mon 15/07/13 LBRA002018 LBRA002018 LBRA002018 LBRA002018 LBRA002019 LBRA0		RSA 4 / Defect Period Review		Fri 12/12/14		
Design Weed 22/05/13 Construction RSA 4 / Defect Period Review Fri 12/07/13 Mill Lane Shryes Corner, Colne Engaine Signage works (inc. design) Mon 15/07/13 LBRA002016 1 Design Construction Mon 15/07/13 LBRA002017 3 Parknall Road / Church Road, Gosfield Signage works (inc. design) Tue 16/07/13 LBRA002017 3 Design Construction Wed 22/05/13 LBRA002017 3 RSA 4 / Defect Period Review Signage works (inc. design) Tue 16/07/14 LBRA002018 3 Construction RSA 4 / Defect Period Review Signage works (inc. design) Wed 22/05/13 LBRA002018 Design Construction Wed 17/07/13 LBRA002019 3 RSA 4 / Defect Period Review Signage works (inc. design) Thu 15/07/13 LBRA002019 3 RSA 4 / Defect Period Review Signage works (inc. design) Thu 18/07/13 LBRA002019 3 Birdbrook Road i/w Chapel End Way, Stambourne Signage works (inc. design) Thu 18/07/13 LBRA002019 3 Design	1553	Henney Back Road j/w Moat Lane, Lamarsh	works (inc.	Fri 12/07/13	LBRA002015	£1,000.00
Construction Fri 12/07/13 RSA 4 / Defect Period Review Signage works (inc. design) Fri 11/07/14 Mill Lane Shryves Corner, Colne Engaine Signage works (inc. design) Mon 15/07/13 LBRA002016 Design Wed 22/05/13 LBRA002017 Mon 15/07/13 LBRA002017 RSA 4 / Defect Period Review Signage works (inc. design) Tue 16/07/13 LBRA002017 LBRA002017 Parknall Road / Church Road, Gosfield Signage works (inc. design) Tue 16/07/13 LBRA002017 LBRA002017 Construction Signage works (inc. design) Wed 17/07/13 LBRA002018 IBRA002018 Design Construction Thu 15/05/14 Thu 15/05/14 IBRA002019 RSA 4 / Defect Period Review Signage works (inc. design) Thu 118/07/13 LBRA002019 RSA 4 / Defect Period Review Signage works (inc. design) Thu 118/07/13 LBRA002019		Design		Wed 22/05/13		
RSA 4 / Defect Period Review Signage works (inc. design) Mon 15/07/13 LBRA002016 Signage works (inc. design) Mon 15/07/13 LBRA002017 Mon 15/07/13 LBRA002018 Mon 15/07/13 LBRA002019 Mon 15/05/13 LBRA002019 LBRA002		Construction		Fri 12/07/13		
Mill Lane Shryves Corner, Colne Engaine Signage works (inc. design) Mon 15/07/13 LBRA002016 16 Design Construction Mon 15/07/13 LBRA002017 13 RSA 4 / Defect Period Review Signage works (inc. design) Tue 16/07/13 LBRA002017 14 Parknall Road / Church Road, Gosfield Signage works (inc. design) Tue 16/07/13 LBRA002017 15 Construction RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/14 LBRA002018 15 Construction Oesign Wed 17/07/13 LBRA002018 16 16 RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/13 LBRA002019 17 RSA 4 / Defect Period Review Signage works (inc. design) Thu 18/07/13 LBRA002019 17 Birdbrook Road I/w Chapel End Way, Stambourne Signage works (inc. design) Thu 18/07/13 LBRA002019 17 Design Wed 22/05/13 Wed 22/05/13 18 18 18 Design Wed 22/05/13 18 18 18 18		RSA 4 / Defect Period Review		Fri 11/07/14		
Design Wed 22/05/13 Construction Signage works (inc. design) Wed 22/05/13 RSA 4 / Defect Period Review Signage works (inc. design) Tue 16/07/14 Parknall Road / Church Road, Gosfield Signage works (inc. design) Tue 16/07/13 Design Wed 22/05/13 LBRA002017 Construction Tue 16/07/14 RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/13 Construction Wed 22/05/13 LBRA002018 RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/13 RSA 4 / Defect Period Review Signage works (inc. design) Thu 18/07/13 Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Thu 18/07/13 Design Thu 18/07/13 LBRA002019 Construction Thu 18/07/13	1554	Mill Lane Shryves Corner, Colne Engaine	works (inc.	Mon 15/07/13	LBRA002016	£1,000.00
Construction Mon 15/07/13 RSA 4 / Defect Period Review Signage works (inc. design) Tue 16/07/14 LBRA002017 14 Parknall Road / Church Road, Gosfield Signage works (inc. design) Tue 16/07/13 LBRA002017 14 Construction RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/13 LBRA002018 15 Church End (near churchyard and by field gate opposite church), Panfield Signage works (inc. design) Wed 17/07/13 LBRA002018 15 Construction RSA 4 / Defect Period Review Thu 15/05/13 LBRA002019 15 Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Thu 18/07/13 LBRA002019 15 Design Wed 22/05/13 Thu 18/07/13 LBRA002019 15		Design		Wed 22/05/13		
RSA 4 / Defect Period Review Signage works (inc. design)		Construction		Mon 15/07/13		
Parknall Road / Church Road, Gosfield Signage works (inc. design) Tue 16/07/13 LBRA002017 14 Design Construction Tue 16/07/13 LBRA002018 15 RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/13 LBRA002018 15 Church End (near churchyard and by field gate opposite church), Panfield Signage works (inc. design) Wed 17/07/13 LBRA002018 15 Design Construction Thu 15/05/14 Thu 15/05/14 1BRA002019 15 Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Thu 18/07/13 LBRA002019 17 Design Wed 22/05/13 Wed 22/05/14 18 18 Construction Thu 18/07/13 Thu 18/07/13 Thu 18/07/13		RSA 4 / Defect Period Review		Mon 14/07/14		
Design Wed 22/05/13 Construction RSA 4 / Defect Period Review Tue 16/07/13 LBRA002018 RSA 4 / Defect Period Review Signage works (inc. design) Wed 17/07/13 LBRA002018 Church End (near church), Panfield Wed 17/07/13 LBRA002018 Design Wed 17/07/13 Thu 15/05/14 RSA 4 / Defect Period Review Signage works (inc. design) Thu 18/07/13 LBRA002019 Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Thu 18/07/13 LBRA002019 Design Construction Thu 18/07/13 Thu 18/07/13	1555	Parknall Road / Church Road, Gosfield	works (inc.	Tue 16/07/13	LBRA002017	£1,000.00
Construction RSA 4 / Defect Period Review Church End (near churchyard and by field gate opposite church), Panfield Design Construction RSA 4 / Defect Period Review Construction Construction Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Design Construction Thu 18/07/13 Thu 18/07/13 Thu 18/07/13 Thu 18/07/13 Thu 18/07/13		Design		Wed 22/05/13		
RSA 4 / Defect Period Review Church End (near churchyard and by field gate opposite church), Panfield Opposite church), Panfield Design Construction RSA 4 / Defect Period Review Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Design Construction Thu 18/07/13 Wed 22/05/13 Wed 22/05/13 Thu 18/07/13 Thu 18/07/13 Thu 18/07/13		Construction		Tue 16/07/13		
Church End (near churchyard and by field gate opposite church), PanfieldSignage works (inc. design)Wed 17/07/13LBRA002018Design Construction RSA 4 / Defect Period ReviewSignage works (inc. design)Thu 18/07/13LBRA002019Birdbrook Road j/w Chapel End Way, Stambourne 		RSA 4 / Defect Period Review		Tue 15/07/14		
Opposite church), Pamfield Design Construction RSA 4 / Defect Period Review Birdbrook Road j/w Chapel End Way, Stambourne Design Construction Thu 18/07/13 Wed 22/05/13 Thu 18/07/13 Thu 18/07/13	1556		works (inc.	Wed 17/07/13	LBRA002018	£1,000.00
Construction RSA 4 / Defect Period Review Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Design Construction Thu 15/05/14 LBRA002019 Wed 22/05/13 Thu 18/07/13		opposite church), Pantield		Wed 22/05/13		
RSA 4 / Defect Period Review Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Design Construction Thu 15/05/14 Thu 18/07/13 LBRA002019 Thu 18/07/13		Design		Wed 22/03/13		
Birdbrook Road j/w Chapel End Way, Stambourne Signage works (inc. design) Thu 18/07/13 LBRA002019 Design Construction		RSA 4 / Defect Period Review		Thu 15/05/14		
Birdbrook Koad J/W Chapel End Way, Stambourne Signage Works (inc. design) Wed 22/05/13 Construction				TL:: 10/01/13	01000000	2 000
	1557	Birdbrook Road j/w Chapel End Way, Stambourne	Signage works (inc. design)	I un 18/0//13	LBKAUUZUIS	£1,000.00
		Design		Wed 22/05/13		
		Construction		Thu 18/07/13		

DC1558 A1124 U Design Constru RSA 4 / D DC1559 Witham Constru RSA 4 / D DC1560 Honeysu Constru RSA 4 / D DC1561 Bramble DC1563 Atlas / D DC1563 Atlas / D DC1704 School Re	A1124 Upper Holt Street, Earls Colne Design Construction RSA 4 / Defect Period Review	Bus stop improvements	Tue 30/04/13	IBRADOSOOS	Sudger
	gn struction / Defect Period Review	Bus stop improvements	Tue 30/04/13	I PD ANNENNE	
	struction / Defect Period Review			LDNAVCJOOC	£4,000.00
	/ Defect Period Review		Thu 25/04/13		
			Tue 30/04/13		
			Wed 01/05/14		
Property of the Control of the Contr	Witham Road near J/w Meadow Way, Black Notely	Bus stop improvements	Tue 30/04/13	LBRA005007	£10,000.00
	uB		Thu 25/04/13		
	Construction		Tue 30/04/13		
	RSA 4 / Defect Period Review		Wed 01/05/14		
To a contract of the contract	Honeysuckle Way Shop, Honeysuckle Way, Witham	Bus stop improvements - raised kerbs	Wed 07/08/13	IRRADOSODR	63 500 00
	UB				2000
	Construction		Mod 07/09/13		
	RSA 4 / Defect Period Review		Thu 08/08/14		
	Bramble Road, Witham	Bus stop improvements	Mon 12/08/13	RRADOGODO	£2 E00 00
	uß		Wed 22/05/13	LBRAUUSUUS	£3,500.00
	Construction		Mon 12/08/13		
	RSA 4 / Defect Period Review		Mon 05/05/14		
	The Kennels Bus Stop, A1124 Haistead Road, Opp	G			
	udley Road, Earls Coine	bus stop improvements	Tue 30/04/13	LBRA005011	£7,500.00
	us		Thu 25/04/13		
	Construction		Tue 30/04/13		
	d Review		Wed 01/05/14		
	oad, Rayne	Signage works (inc. design)	Wed 29/01/14	LBRA001002	£3,000.00
Design	LS.		Fri 29/11/13		
V A 20	CAN A Profession		Wed 29/01/14		
DC1705 BRA27.	BRA27-Batt Hall (Bulmer Road Bulmer)	Control limit	Wed 28/01/15		
			Fri 07/03/14	LBKA002020	£10,000.00
Const	Construction		Fri 07/03/14		
RSA 4 /	RSA 4 / Defect Period Review		Fri 06/03/15		
DC1706 BRA28-	gham Drive, Earls Coine at j/w A1124	100			
		olgnage Works (inc. design)	lue 24/12/13	LBRA002021	£2,000.00
Design	uŝ.		Thu 31/10/13		
Const	Construction		Tue 24/12/13		
DC1707 R1034	Forte Colon to Connection Boost		Tue 23/12/14		
	Design	Lining Works	Fri 25/10/13	LBRA002025	£2,000.00
Const	truction		Fri 25/10/13		
RSA 4 /	RSA 4 / Defect Period Review		Fri 24/10/14		
DC1709 Newlar	Newland Street, Witham	Dropped Kerbs	Tue 21/01/14	LBRA002028	£2,000.00
Design	us.		Fri 29/11/13		
Const	Construction		Tue 21/01/14		
RSA 4 /	RSA 4 / Detect Period Review		Tue 20/01/15		
Oak Ro	Oak Road Railway Bridge, Rivenhall	ITS - Signal Controlled one way	To be programmed	LBRA002023	£45,000.00
7,784	27 & 28 Halstoad	PROW - drainage	To be programmed	LBRADOSOOI	
	7 Br. 1		To be programmed	LBACOSOO	
Flora R	Flora Road/Bramble Road Shelter	Ric Stor Improvements	Med 28/08/13	I BRADOSO17	67 E00 00
Flora R	Flora Road/Shelter Adi. to Rosebay Close	Bus Stop Improvements	Wed 28/08/13	I BRADDS016	£7,500.00
Cruch	Cruch Croft/Rowlev Hill Sturmer Shelter	Bus Stop Improvements	Wed 28/08/13	I BRADDSD04	£10,000,00
Upper	Upper Holt Street Shelter	Bus Stop Improvements	Wed 20/03/13	LBRA005006	£4,000.00
Pennyr	Pennyroyal Crescent Shelter	Bus Stop Improvements	Mon 11/02/13	LBRA005004	£7,500.00
Church	Church End Panifield Shelter	Bus Stop Improvements	Wed 28/08/13	LBRA005013	£7,500.00
Halste	Halstead Hospital shelter	Bus Stop Improvements	Mon 18/11/13	LBRA005002	£10,000.00
Lauren	Laurence Avenue shelter	Bus Stop Improvements	Fri 06/09/13	LBRA005015	£7,500.00
	White Horse Ave. Halstead	Bus Stop Improvements	Fri 30/08/13	LBRA005012	£7,500.00
DC76 The Ma	The Maltings Rayne	Pedestrian refuge	Fri 07/09/12	HB09124	£12,723.00
Design			Fri 29/06/12		
Cons	Construction BSA / Defeat Beriam		Wod 22/04/14		
DC242 Inwort	Inworth Road, Feering - DESIGN ONLY	Footway (new)	Mon 24/06/13	H810158	£33,228.00
	L81		Mon 03/06/13		
DC1003 Priory	Priory Hall, Colchester Road, Halstead	Pedestrian Crossing improvements	Fri 10/05/13	HB12048	£12,003.00
Design	gn 		Fri 01/03/13		
RSA 4 /	Construction RSA 4 / Defect Period Review		Mon 12/05/14		
DC1119 Maldor	Maldon Road, Witham	Footway Improvements	Wed 02/01/13	HB12020	£10.082.00
	ug		Wed 31/10/12		
Const	Construction		Wed 02/01/13		

Design					
Eaterance	Task Name	Works Description	Ģ.	Cost Code	Allocated
Number					Sudget
DC58	Rayne Road, Braintree	Pedestrian refuge	Fri 25/01/13	H810173	£0.00
	RSA 4 / Defect Period Review		Thu 23/01/14		
DC82	Mill Park Drive, Braintree	Traffic calming	Fri 25/01/13	HB10118	£0.00
	RSA 4 / Defect Period Review)	Thu 23/01/14		
DC1486A	A1017 Rowley Hill, Sturmur (o/s Riverside Bungalows)	Layby works	Tue 03/09/13	HB08278	£12,818.00
	Design		Fri 14/06/13	L	
	Construction		Tue 03/09/13		
	RSA 4 / Defect Period Review		Tue 02/09/14		
DC1486B	A1017 Rowley Hill, Sturmur (in vicinity of property "Long Lindeth")	Signage works (inc. design)	Fri 30/08/13	HB08278	£5,000.00
	Design		Fri 14/06/13		
	Construction		Fri 30/08/13		
	RSA 4 / Defect Period Review		Fri 29/08/14		
DC1294	Clockhouse Way, Braintree	Footway improvements	Mon 09/09/13	HB12019	£15,345.00
	Design		Fri 21/06/13		
	Construction		Mon 09/09/13		
	RSA 4 / Defect Period Review		Mon 08/09/14		